



Shop Name: --
Tel: --
Email: --
Address: --

Report ID: MAXIA20260922155217
Test Time: 2026-09-22 15:52:17
Technician: Sbu

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Swift/--
VIN: MBHCZC63S00462931

Odometer Reading: 74158
License Plate: KP95RFGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
ECM/PCM(Engine/powertrain)	 0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	 0
SRS(Airbag)	 0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	 0
EPS(Power steering)	 0
BCM(Body Control Module)	 0
SMK(Immobilizer and/or keyless system)	 0

DTC (0)

Technician Notes

2017302363

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

