

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Swift/--
VIN: MBHCZC63S00A72751

Odometer Reading: 97417
License Plate: HJK145L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V4.91

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
ECM/PCM(Engine/powertrain)	0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	2
SRS(Airbag)	0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	1
CGW(Central gateway control module)	1
EPS(Power steering)	0
BCM(Body Control Module)	0
SMK(Immobilizer and/or keyless system)	0

DTC (4)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (2 DTCs)

DTC	Description	Status
C1037	Steering angle sensor power supply voltage	History
C1057	Power supply voltage	History

IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A) (1 DTC)

DTC	Description	Status
B1840	Vehicle speed data invalid	History

CGW(Central gateway control module) (1 DTC)

DTC	Description	Status
U0155-87	Lost communication with Instrument Panel Cluster (IPC) control module	History

Technician Notes

2017305123

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.