

Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Suzuki/Swift/--

VIN: MBHCZC63S00C97830

Odometer Reading: 154797

License Plate: LR49FNGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V4.91

Repair Order Number: --



System Scanned (7)

System	Status/DTC
ECM/PCM(Engine/powertrain)	✓ 0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	✗ 3
SRS(Airbag)	✗ 1
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	✓ 0
EPS(Power steering)	✓ 0
BCM(Body Control Module)	✓ 0
SMK(Immobilizer and/or keyless system)	✓ 0



DTC (4)

ABS/ESP(Anti-lock Braking System / Electronic Stability Program) (3 DTCs)

DTC	Description	Status
C1091	CAN invalid data from ECM	History
C1037	Steering angle sensor power supply voltage	History
C1057	Power supply voltage	History

SRS(Airbag) (1 DTC)

DTC	Description	Status
B1004-18	Power source voltage too low	History

Technician Notes

2017305270

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.