Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261026134140
Test Time: 2026-10-26 13:41:40
Technician: Werner

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/Datsun Go/--
VIN: MDHJBAAD0Z0503418

Odometer Reading: 151942km
License Plate: KFD378MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.71

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
Engine	0
ABS	1
Air bag	1
Meter/M&A	0
Electric Power Steering (EPS)/DAST 3	1
BCM	0
IPDM E/R	1

DTC (4)

ABS (1 DTC)

DTC	Description	Status
C1109	Battery voltage (abnormal)	Past

Air bag (1 DTC)

DTC	Description	Status
B142A:16	Ignition voltage	Past

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
C1608	Control unit	Past

IPDM E/R (1 DTC)

DTC	Description	Status
B2099	Ignition relay OFF circuit	Past

Technician Notes

2017317127

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.