

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/KWID/--
VIN: MEEBBA00100569562

Odometer Reading: 55907km
License Plate: HL46XJGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
INJ(Injection)	 21
ABG(Airbag / pretensioners)	 2
TDB(Instrument panel)	 5
UCH(Central control unit)	 3
DAV(Variable power assist steering)	 1
RDO(Radio)	 3

DTC (35)

INJ(Injection) (21 DTCs)

DTC	Description	Status
DTC009517	Air temperature sensor circuit Signal outside upper limit	Memory
DTC010516	Inlet manifold pressure sensor circuit Signal outside lower limit	Memory
DTC010664	Inlet pressure consistency Value outside tolerances.	Active
DTC011517	Water temperature sensor circuit Voltage too high.	Memory
DTC012029	Throttle potentiometer circuit track 1 Signal incoherence.	Memory
DTC014113	Downstream oxygen sensor heating circuit Open circuit	Memory
DTC022029	Throttle potentiometer circuit track 2 Signal incoherence.	Memory

DTC0226F3	Brake/accelerator pedal positions Fault on gangs 1 and 2 of the pedal potentiometer.	Memory
DTC033531	Engine speed sensor signal No signal	Memory
DTC033564	Engine speed sensor signal Plausibility.	Memory
DTC035311	Cylinder 3 ignition coil circuit Short circuit to earth.	Memory
DTC035313	Cylinder 3 ignition coil circuit Open circuit	Memory
DTC056016	Computer supply voltage Permanent low level	Memory
DTC060AF1	Computer Safety mode 1 flag	Memory
DTC061A61	Computer Signal calculation failure	Memory
DTC064116	Sensor supply No.1 voltage Below the min level	Memory
DTC065116	Sens. supply No.2 voltage Below the min level	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Memory
DTC210001	Motorised throttle control circuit General motorised throttle control fault	Memory
DTC213564	Pedal/throttle position coherence Signal incoherence.	Memory
DTC250217	Alternator power available info Circuit voltage above threshold	Memory

ABG(Airbag / pretensioners) (2 DTCs)

DTC	Description	Status
DTC80D223	Warning light circuit fault Inconsistency between the warning light status transmitted by the instrument panel and the request made by the airbag computer.	Memory
DTCF00316	Computer supply voltage Feed voltage too low	Memory

TDB(Instrument panel) (5 DTCs)

DTC	Description	Status
-----	-------------	--------

DTC940213	Fuel sender circuit Open circuit	Memory
DTC94037B	Brake fluid level circuit Below the min level	Memory
DTC941111	Oil pressure sensor circuit Short circuit to earth.	Memory
DTCC00187	CAN communication Signal missing.	Memory
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory

UCH(Central control unit) (3 DTCs)

DTC	Description	Status
DTC953019	Left indicator circuit Circuit current above threshold	Memory
DTC953118	Right indicator circuit Circuit current below threshold	Memory
DTC95F031	Transponder supply circuit No signal	Memory

DAV(Variable power assist steering) (1 DTC)

DTC	Description	Status
DTC560849	Computer Internal electronic failure	Memory

RDO(Radio) (3 DTCs)

DTC	Description	Status
DTC932813	Microphone Open circuit	Memory
DTC934262	Unit locked Computer locked	Memory
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory

Technician Notes

2017302016

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.