Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/KWID/--
VIN: MEEBBA002K8685986

Odometer Reading: 101525km
License Plate: JL85DXGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
INJ(Injection)	8
ABS(Anti-lock braking system)	3
ABG(Airbag / pretensioners)	3
TDB(Instrument panel)	3
UCH(Central control unit)	2
DAV(Variable power assist steering)	2
RDO(Radio)	7

DTC (28)

INJ(Injection) (8 DTCs)

DTC	Description	Status
DTC0226F1	Brake/accelerator pedal positions Safety mode 1 flag	Memory
DTC033531	Engine speed sensor signal No signal	Memory
DTC056016	Computer supply voltage Permanent low level	Memory
DTC060AF1	Computer Safety mode 1 flag	Memory
DTC061A61	Computer Signal calculation failure	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Memory
DTC250217	Alternator power available info Circuit voltage above threshold	Memory

DTCC31587	Vehicle speed multiplexed information Missing message	Memory

ABS(Anti-lock braking system) (3 DTCs)

DTC	Description	Status
DTC512764	Wheel speed coherence Signal plausibility failure	Memory
DTCC00100	Multiplexed network No communication	Memory
DTCC07300	Multiplexed network Bus off	Memory

ABG(Airbag / pretensioners) (3 DTCs)

DTC	Description	Status
DTC903616	Power supply voltage Circuit voltage below threshold	Memory
DTCC14087	No UCH multiplex signal Missing message	Memory
DTCC15587	Instrument panel multiplexed emission absent Missing message	Memory

TDB(Instrument panel) (3 DTCs)

DTC	Description	Status
DTC941111	Oil pressure sensor circuit Short circuit to earth.	Memory
DTCC00187	CAN communication Signal missing.	Memory
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory

UCH(Central control unit) (2 DTCs)

DTC	Description	Status
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC95F031	Transponder supply circuit No signal	Memory

DAV(Variable power assist steering) (2 DTCs)

DTC	Description	Status
DTC560849	Computer Internal electronic failure	Memory
DTCC14087	No UCH multiplex signal Missing message	Memory

RDO(Radio) (7 DTCs)

DTC	Description	Status
DTC930D11	Right front speaker Short circuit to earth.	Memory
DTC930D13	Right front speaker Open circuit	Memory
DTC930D1C	Right front speaker Short circuit	Memory
DTC930F11	Left front speaker Short circuit to earth.	Memory
DTC930F13	Left front speaker Open circuit	Memory
DTC934262	Unit locked Computer locked	Memory
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory

Technician Notes
2017316150

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.