

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/KWID/--
VIN: MEEBBA00900836639

Odometer Reading: 14857km
License Plate: LP04XSGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
INJ(Injection)	 14
ABS(Anti-lock braking system)	 9
ABG(Airbag / pretensioners)	 3
TDB(Instrument panel)	 4
UCH(Central control unit)	 2
DAV(Variable power assist steering)	 5

DTC (37)

INJ(Injection) (14 DTCs)

DTC	Description	Status
DTC012029	Throttle potentiometer circuit track 1 Signal incoherence.	Memory
DTC013513	Upstream oxygen sensor heating circuit Open circuit	Memory
DTC022029	Throttle potentiometer circuit track 2 Signal incoherence.	Memory
DTC022516	Pedal potentiometer circuit track 1 Battery voltage too low	Memory
DTC0226F3	Brake/accelerator pedal positions Fault on gangs 1 and 2 of the pedal potentiometer.	Memory
DTC033531	Engine speed sensor signal No signal	Memory
DTC033564	Engine speed sensor signal Plausibility.	Memory

DTC056016	Computer supply voltage Permanent low level	Memory
DTC060AF1	Computer Safety mode 1 flag	Memory
DTC061A61	Computer Signal calculation failure	Memory
DTC064116	Sensor supply No.1 voltage Below the min level	Memory
DTC065116	Sens. supply No.2 voltage Below the min level	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Memory
DTC212016	Pedal potentiometer circuit track 2 Voltage too low.	Memory

ABS(Anti-lock braking system) (9 DTCs)

DTC	Description	Status
DTC402004	Pump motor control circuit Pump fault	Memory
DTC40201C	Pump motor circuit Feed voltage too high	Memory
DTC403438	Front right wheel speed sensor frequency Signal detected outside upper or lower limit.	Active
DTC403713	Rear left hand wheel speed sensor circuit Open circuit	Memory
DTC40371D	Rear left hand wheel speed sensor circuit Short circuit	Memory
DTC403738	Rear left wheel speed sensor frequency Fault on wheel speed sensor circuit	Memory
DTC505004	Computer ECU fault.	Memory
DTCC10000	Injection multiplexed emission missing No communication	Memory
DTCC42200	Invalid UCH multiplex signals ABS multiplex invalid signals	Memory

ABG(Airbag / pretensioners) (3 DTCs)

DTC	Description	Status
DTC80D223	Warning light circuit fault Signal low	Memory

DTC903616	Power supply voltage Circuit voltage below threshold	Memory
DTC903617	Power supply voltage Circuit voltage above threshold	Memory

TDB(Instrument panel) (4 DTCs)

DTC	Description	Status
DTC940213	Fuel sender circuit Open circuit	Memory
DTC94037B	Brake fluid level circuit Below the min level	Memory
DTC941111	Oil pressure sensor circuit Short circuit to earth.	Memory
DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (2 DTCs)

DTC	Description	Status
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC95B224	Reverse gear circuit	Memory

DAV(Variable power assist steering) (5 DTCs)

DTC	Description	Status
DTC560116	Battery voltage 12 V Battery voltage too low	Memory
DTC560117	Computer power supply Battery voltage too high	Memory
DTC561B86	Info. multiplex vehicle speed invalid Invalid signal	Memory
DTCE14087	120 ECM not detected by 1232 EPS CAN-V1 Missing message	Memory
DTCE14F87	645 BCM not detected by 1232 EPS CAN-V1 Missing message	Memory

Technician Notes

2017304181

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.