Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEEHBC00000113963

Odometer Reading: 35892km
License Plate: LCW020MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
INJ(Injection)	4
ABS(Anti-lock braking system)	0
ABG(Airbag / pretensioners)	0
TDB(Instrument panel)	1
UCH(Central control unit)	8
UCC(Communications unit) ADAS	1
DAV(Variable power assist steering)	0
GW2(Central gateway)	0
HFM(Hands-free module)	0

DTC (14)

INJ(Injection) (4 DTCs)

DTC	Description	Status
DTC0226F1	Brake/accelerator pedal positions Safety mode 1 flag	Memory
DTC073696	Gear r speed coherence Mechanical failures	Memory
DTC090196	Clutch motor Clutch overheating	Memory
DTC09141C	Gear engagement sensor Circuit voltage outside limits	Memory

TDB(Instrument panel) (1 DTC)

DTC	Description	Status

DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (8 DTCs)

DTC	Description	Status
DTC5A607B	Under-inflated Low fluid level	Active
DTC5A727A	Wheel 1 flat Fluid leak or sealing failure	Memory
DTC5A737A	Wheel 2 flat Fluid leak or sealing failure	Memory
DTC5A747A	Wheel 3 flat Fluid leak or sealing failure	Memory
DTC5A8368	Wheel valve sensor 2 Event signal	Memory
DTC5A8468	Wheel valve sensor 3 Event signal	Memory
DTC956401	Brake pedal contact circuit	Memory
DTC95A064	Rear screen wiper circuit	Memory

UCC(Communications unit) (1 DTC)

DTC	Description	Status
DTC930B1C	Right rear speaker General electrical failure	Memory

Technician Notes

2017317275

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.