

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEEHBC00200027778

Odometer Reading: 97835km
License Plate: KG92NGGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
INJ(Injection)	 0
ABS(Anti-lock braking system)	 2
ABG(Airbag / pretensioners)	 3
TDB(Instrument panel)	 2
UCH(Central control unit)	 3
UCC(Communications unit)	  4
DAV(Variable power assist steering)	 4
GW2(Central gateway)	 0
HFM(Hands-free module)	 3

DTC (21)

ABS(Anti-lock braking system) (2 DTCs)

DTC	Description	Status
DTC505616	Computer supply voltage Circuit voltage below threshold	Memory
DTC505617	Computer supply voltage Circuit voltage above threshold	Memory

ABG(Airbag / pretensioners) (3 DTCs)

DTC	Description	Status
DTC80D223	Warning light circuit fault Signal low	Memory
DTC80D224	Warning light circuit fault Signal high	Memory

DTC903616	Power supply voltage Circuit voltage below threshold	Memory
-----------	---	--------

TDB(Instrument panel) (2 DTCs)

DTC	Description	Status
DTC941113	Oil pressure sensor circuit Open circuit	Memory
DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (3 DTCs)

DTC	Description	Status
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC953211	Boot opening control Short circuit to earth.	Memory
DTC956301	Brake pedal contact circuit	Memory

UCC(Communications unit) (4 DTCs)

DTC	Description	Status
DTC930B1C	Right rear speaker General electrical failure	Memory
DTC930D1C	Right front speaker General electrical failure	Memory
DTC930F1C	Left front speaker General electrical failure	Memory
DTC93111C	Left rear speaker General electrical failure	Memory

DAV(Variable power assist steering) (4 DTCs)

DTC	Description	Status
DTC560116	Battery voltage 12 V Battery voltage too low	Memory
DTC561A82	Vehicle speed multiplexed information Sequence counter active/incorrect/not updated	Memory
DTC561B86	Info. multiplex vehicle speed invalid Invalid signal	Memory
DTCE14F87	645 BCM not detected by 1232 EPS CAN-V1 Missing message	Memory

HFM(Hands-free module) (3 DTCs)

DTC	Description	Status
-----	-------------	--------

DTCA05111	VER(Steering lock) Short circuit to earth.	Memory
DTCA0571C	Steering column lock protection Circuit voltage outside limits	Memory
DTCA05985	Steering column lock protection Signal above the authorised threshold	Memory

Technician Notes
2017302489

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.