

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEEHBC00300032827

Odometer Reading: 66401km
License Plate: KJ76TYGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
INJ(Injection)	 0
ABS(Anti-lock braking system)	 0
ABG(Airbag / pretensioners)	 0
TDB(Instrument panel)	 1
UCH(Central control unit)	 0
UCC(Communications unit)	  2
DAV(Variable power assist steering)	 0
GW2(Central gateway)	 0
HFM(Hands-free module)	 0

DTC (3)

TDB(Instrument panel) (1 DTC)

DTC	Description	Status
DTC941113	Oil pressure sensor circuit Open circuit	Active

UCC(Communications unit) (2 DTCs)

DTC	Description	Status
DTC934116	Computer Circuit voltage below threshold	Memory
DTC93514B	Computer Overheating	Memory

Technician Notes
2017302308

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.