

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEERBC00000121761

Odometer Reading: 95030km
License Plate: LY82PFGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
INJ(Injection)	 9
ABS(Anti-lock braking system)	 16
ABG(Airbag / pretensioners)	 3
TDB(Instrument panel)	 2
UCH(Central control unit)	 2
DAV(Variable power assist steering)	 5
RDO(Radio)	 3

AQAS

DTC (40)

INJ(Injection) (9 DTCs)

DTC	Description	Status
DTC013011	Upstream oxygen sensor circuit Short circuit to earth.	Memory
DTC013612	Downstream oxygen sensor circuit Short-circuit to +12V	Active
DTC013613	Downstream oxygen sensor circuit Open circuit	Active
DTC014113	Downstream oxygen sensor heating circuit Open circuit	Memory
DTC017009	Fuel circuit functional fault Component failures	Memory
DTC056016	Computer supply voltage Permanent low level	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Memory

DTC250479	Battery voltage 12 V Mechanical failures	Memory
DTCC31587	Vehicle speed multiplexed information Missing message	Memory

ABS(Anti-lock braking system) (16 DTCs)

DTC	Description	Status
DTC402004	Pump motor control circuit Pump fault	Memory
DTC40201C	Pump motor circuit Feed voltage too high	Memory
DTC403113	Front left hand wheel speed sensor circuit Open circuit	Memory
DTC40311D	Front left hand wheel speed sensor circuit Short circuit	Memory
DTC403413	Front R/H wheel speed sensor circuit Open circuit	Memory
DTC40341D	Front R/H wheel speed sensor circuit Short circuit	Memory
DTC403713	Rear left hand wheel speed sensor circuit Open circuit	Memory
DTC40371D	Rear left hand wheel speed sensor circuit Short circuit	Memory
DTC403A13	Rear right hand wheel speed sensor circuit Open circuit	Memory
DTC403A1D	Rear right hand wheel speed sensor circuit Short circuit	Memory
DTC505004	Computer ECU fault.	Memory
DTC512764	Wheel speed coherence Signal plausibility failure	Memory
DTCC10000	Injection multiplexed emission missing No communication	Memory
DTCC40100	Invalid INJ. Multiplex signals ABS multiplex invalid signals	Memory
DTCC42200	Invalid UCH multiplex signals ABS multiplex invalid signals	Memory
DTCF00313	Computer power supply Open circuit	Memory

ABG(Airbag / pretensioners) (3 DTCs)

DTC	Description	Status
DTC903616	Power supply voltage Circuit voltage below threshold	Memory
DTC903617	Power supply voltage Circuit voltage above threshold	Memory
DTCC12187	ABS/ESP multiplex transmission absent Missing message	Memory

TDB(Instrument panel) (2 DTCs)

DTC	Description	Status
DTC941113	Oil pressure sensor circuit Open circuit	Memory
DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (2 DTCs)

DTC	Description	Status
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC953018	Left indicator circuit Circuit current below threshold	Active

DAV(Variable power assist steering) (5 DTCs)

DTC	Description	Status
DTC560116	Battery voltage 12 V Battery voltage too low	Memory
DTC560849	Computer Internal electronic failure	Memory
DTC561B86	Info. multiplex vehicle speed invalid Invalid signal	Memory
DTCE14087	120 ECM not detected by 1232 EPS CAN-V1 Missing message	Memory
DTCE14F87	645 BCM not detected by 1232 EPS CAN-V1 Missing message	Memory

RDO(Radio) (3 DTCs)

DTC	Description	Status
DTC932413	GPS aerial circuit Open circuit	Active
DTC932813	Microphone Open circuit	Memory

DTC934262 Unit locked
Computer locked

Active

Technician Notes
2017305148

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.