Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEERBC00300208554

Odometer Reading: 90808km
License Plate: LY31YJGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
INJ(Injection)	7
ABS(Anti-lock braking system)	2
ABG(Airbag / pretensioners)	1
TDB(Instrument panel)	1
UCH(Central control unit)	9
DAV(Variable power assist steering)	1
RDO(Radio)	3

DTC (24)

INJ(Injection) (7 DTCs)

DTC	Description	Status
DTC013011	Upstream oxygen sensor circuit Short circuit to earth.	Memory
DTC013611	Downstream oxygen sensor circuit Short circuit to earth.	Memory
DTC017009	Fuel circuit functional fault Component failures	Memory
DTC035311	Cylinder 3 ignition coil circuit Short circuit to earth.	Memory
DTC035313	Cylinder 3 ignition coil circuit Open circuit	Memory
DTC056016	Computer supply voltage Permanent low level	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Memory

ABS(Anti-lock braking system) (2 DTCs)

DTC	Description	Status
DTC40201C	Pump motor circuit Feed voltage too high	Memory
DTCF00313	Computer power supply Open circuit	Memory

ABG(Airbag / pretensioners) (1 DTC)

DTC	Description	Status
DTC903616	Power supply voltage Circuit voltage below threshold	Memory

TDB(Instrument panel) (1 DTC)

DTC	Description	Status
DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (9 DTCs)

DTC	Description	Status
DTC5A607B	Under-inflated Low fluid level	Memory
DTC5A727A	Wheel 1 flat Fluid leak or sealing failure	Memory
DTC5A737A	Wheel 2 flat Fluid leak or sealing failure	Memory
DTC5A747A	Wheel 3 flat Fluid leak or sealing failure	Memory
DTC5A757A	Wheel 4 flat Fluid leak or sealing failure	Memory
DTC5A8368	Wheel valve sensor 2 Event signal	Memory
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC956123	End of clutch switch travel circuit	Memory
DTC95F031	Transponder supply circuit	Memory

DAV(Variable power assist steering) (1 DTC)

DTC	Description	Status
DTC560116	Battery voltage 12 V Battery voltage too low	Memory

RDO(Radio) (3 DTCs)

DTC	Description	Status

DTC932813	Microphone Open circuit	Memory
DTC934262	Unit locked Computer locked	Memory
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory

Technician Notes

2017306227

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.