Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEERBC00400189898

Odometer Reading: 156409km
License Plate: LW47FFGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
INJ(Injection)	25
ABS(Anti-lock braking system)	4
ABG(Airbag / pretensioners)	5
TDB(Instrument panel)	2
UCH(Central control unit)	10
DAV(Variable power assist steering)	5
RDO(Radio)	4
HFM(Hands-free module)	4

DTC (59)

INJ(Injection) (25 DTCs)

DTC	Description	Status
DTC001013	Intake camshaft shifter circuit Open circuit	Memory
DTC009517	Air temperature sensor circuit Signal outside upper limit	Memory
DTC010516	Inlet manifold pressure sensor circuit Signal outside lower limit	Memory
DTC01061C	Inlet pressure consistency Abnormal voltage.	Memory
DTC012029	Throttle potentiometer circuit track 1 Signal incoherence.	Memory
DTC013011	Upstream oxygen sensor circuit Short circuit to earth.	Memory

DTC013513	Upstream oxygen sensor heating circuit Open circuit	Memory
DTC013611	Downstream oxygen sensor circuit Short circuit to earth.	Memory
DTC017009	Fuel circuit functional fault Component failures	Memory
DTC020213	Cylinder 2 injector control circuit Open circuit	Memory
DTC022029	Throttle potentiometer circuit track 2 Signal incoherence.	Memory
DTC0302F8	Misfire on cylinder 2 Polluting misfiring.	Memory
DTC035111	Cylinder 1 ignition coil circuit Short circuit to earth.	Memory
DTC035113	Cylinder 1 ignition coil circuit Open circuit	Memory
DTC035211	Cylinder 2 ignition coil circuit Short circuit to earth.	Memory
DTC035213	Cylinder 2 ignition coil circuit Open circuit	Memory
DTC044313	Canister purge solenoid valve circuit Open circuit	Memory
DTC056016	Computer supply voltage Permanent low level	Memory
DTC060AF1	Computer Safety mode 1 flag	Memory
DTC061A61	Computer Signal calculation failure	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Active
DTC210001	Motorised throttle control circuit General motorised throttle control fault	Memory
DTC250421	Battery voltage 12 V Signal amplitude < minimum	Memory
DTCC31582	Vehicle speed multiplexed information Sequence counter active/incorrect/not updated	Memory
DTCC31587	Vehicle speed multiplexed information Missing message	Memory

ABS(Anti-lock braking system) (4 DTCs)

DTC	Description	Status
DTC40311D	Front left hand wheel speed sensor circuit Short circuit	Active
DTC512764	Wheel speed coherence Signal plausibility failure	Memory
DTCC42200	Invalid UCH multiplex signals ABS multiplex invalid signals	Memory
DTCC42300	Invalid tdb multiplex signals ABS multiplex invalid signals	Memory

ABG(Airbag / pretensioners) (5 DTCs)

DTC	Description	Status
DTC802013	Front left-hand chest-level side airbag circuit Open circuit	Memory
DTC80D223	Warning light circuit fault Signal low	Memory
DTC80D224	Warning light circuit fault Signal high	Memory
DTC903616	Power supply voltage Circuit voltage below threshold	Memory
DTC903617	Power supply voltage Circuit voltage above threshold	Memory

TDB(Instrument panel) (2 DTCs)

DTC	Description	Status
DTC941111	Oil pressure sensor circuit Short circuit to earth.	Memory
DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (10 DTCs)

DTC	Description	Status
DTC5A607B	Under-inflated Low fluid level	Memory
DTC5A737A	Wheel 2 flat Fluid leak or sealing failure	Memory
DTC5A8055	Tire pressure monitor function Not configured	Active
DTC5A8268	Wheel valve sensor 1 Event signal	Memory

DTC5A8368	Wheel valve sensor 2 Event signal	Memory
DTC5A8468	Wheel valve sensor 3 Event signal	Memory
DTC5A8568	Wheel valve sensor 4 Event signal	Memory
DTC920F16	Voltage control Circuit voltage below threshold	Memory
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC95A064	Rear screen wiper circuit	Memory

DAV(Variable power assist steering) (5 DTCs)

DTC	Description	Status
DTC560116	Battery voltage 12 V Battery voltage too low	Memory
DTC560849	Computer Internal electronic failure	Memory
DTC561B86	Info. multiplex vehicle speed invalid Invalid signal	Memory
DTCE14087	120 ECM not detected by 1232 EPS CAN-V1 Missing message	Memory
DTCE14F87	645 BCM not detected by 1232 EPS CAN-V1 Missing message	Memory

RDO(Radio) (4 DTCs)

DTC	Description	Status
DTC932813	Microphone Open circuit	Memory
DTC934149	Computer Internal electronic fault	Memory
DTC934262	Unit locked Computer locked	Active
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory

HFM(Hands-free module) (4 DTCs)

DTC	Description	Status
DTCA05111	VER(Steering lock) Short circuit to earth.	Memory
DTCA05267	Steering column lock protection	Memory

DTCA0571C	Steering column lock protection Circuit voltage outside limits	Memory
DTCA05985	Steering column lock protection Signal above the authorised threshold	Memory

Technician Notes

2017314687

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.