Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEERBC00500163830

Odometer Reading: 66768km
License Plate: LF98XMGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
INJ(Injection)	5
ABS(Anti-lock braking system)	2
ABG(Airbag / pretensioners)	4
TDB(Instrument panel)	4
UCH(Central control unit)	1
DAV(Variable power assist steering)	5
RDO(Radio)	0
HFM(Hands-free module)	4

DTC (25)

INJ(Injection) (5 DTCs)

DTC	Description	Status
DTC017009	Fuel circuit functional fault Component failures	Memory
DTC056016	Computer supply voltage Permanent low level	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Memory
DTCC31582	Vehicle speed multiplexed information Sequence counter active/incorrect/not updated	Memory
DTCC31587	Vehicle speed multiplexed information Missing message	Memory

ABS(Anti-lock braking system) (2 DTCs)

DTC	Description	Status

DTC512764	Wheel speed coherence Signal plausibility failure	Memory
DTCC42200	Invalid UCH multiplex signals ABS multiplex invalid signals	Memory

ABG(Airbag / pretensioners) (4 DTCs)

DTC	Description	Status
DTC802013	Front left-hand chest-level side airbag circuit Open circuit	Memory
DTC802813	Front right-hand chest-level side airbag circ. Open circuit	Active
DTC80D223	Warning light circuit fault Signal low	Memory
DTC903616	Power supply voltage Circuit voltage below threshold	Memory

TDB(Instrument panel) (4 DTCs)

DTC	Description	Status
DTC940213	Fuel sender circuit Open circuit	Memory
DTC94037B	Brake fluid level circuit Below the min level	Memory
DTC941113	Oil pressure sensor circuit Open circuit	Memory
DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (1 DTC)

DTC	Description	Status
DTC952014	Starter relay Open circuit or short circuit to earth	Memory

DAV(Variable power assist steering) (5 DTCs)

DTC	Description	Status
DTC560116	Battery voltage 12 V Battery voltage too low	Memory
DTC560849	Computer Internal electronic failure	Memory
DTC561B86	Info. multiplex vehicle speed invalid Invalid signal	Memory
DTCE14087	120 ECM not detected by 1232 EPS CAN-V1 Missing message	Memory

DTCE14F87	645 BCM not detected by 1232 EPS CAN-V1 Missing message	Memory

HFM(Hands-free module) (4 DTCs)

DTC	Description	Status
DTCA0334A	Dongle Installed component incorrect	Memory
DTCA05111	VER(Steering lock) Short circuit to earth.	Memory
DTCA05267	Steering column lock protection	Memory
DTCA0571C	Steering column lock protection Circuit voltage outside limits	Memory

Technician Notes

2017306881

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.