Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/TRIBER/KIGER/--
VIN: MEERBC00600182967

Odometer Reading: 18406km
License Plate: HDZ771L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
INJ(Injection)	5
ABS(Anti-lock braking system)	1
ABG(Airbag / pretensioners)	1
TDB(Instrument panel)	1
UCH(Central control unit)	6
DAV(Variable power assist steering)	5
RDO(Radio) ADAS	4

DTC (23)

INJ(Injection) (5 DTCs)

DTC	Description	Status
DTC017009	Fuel circuit functional fault Component failures	Memory
DTC056016	Computer supply voltage Permanent low level	Memory
DTC060AF1	Computer Safety mode 1 flag	Memory
DTC061A61	Computer Signal calculation failure	Memory
DTC065711	Main relay control circuit Short circuit to earth.	Memory

ABS(Anti-lock braking system) (1 DTC)

DTC	Description	Status
DTC512764	Wheel speed coherence Signal plausibility failure	Memory

ABG(Airbag / pretensioners) (1 DTC)

DTC	Description	Status
DTC903616	Power supply voltage Circuit voltage below threshold	Memory

TDB(Instrument panel) (1 DTC)

DTC	Description	Status
DTCC00187	CAN communication Signal missing.	Memory

UCH(Central control unit) (6 DTCs)

DTC	Description	Status
DTC5A607B	Under-inflated Low fluid level	Memory
DTC5A727A	Wheel 1 flat Fluid leak or sealing failure	Memory
DTC5A737A	Wheel 2 flat Fluid leak or sealing failure	Memory
DTC5A747A	Wheel 3 flat Fluid leak or sealing failure	Memory
DTC5A757A	Wheel 4 flat Fluid leak or sealing failure	Memory
DTC952014	Starter relay Open circuit or short circuit to earth	Active

DAV(Variable power assist steering) (5 DTCs)

DTC	Description	Status
DTC560116	Battery voltage 12 V Battery voltage too low	Memory
DTC560849	Computer Internal electronic failure	Memory
DTC561B86	Info. multiplex vehicle speed invalid Invalid signal	Memory
DTCE14087	120 ECM not detected by 1232 EPS CAN-V1 Missing message	Memory
DTCE14F87	645 BCM not detected by 1232 EPS CAN-V1 Missing message	Memory

RDO(Radio) (4 DTCs)

DTC	Description	Status
DTC932413	GPS aerial circuit Open circuit	Active

DTC932813	Microphone Open circuit	Memory
DTC934262	Unit locked Computer locked	Memory
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory

Technician Notes

2017309928

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.