Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261009135532
Test Time: 2026-10-09 13:55:32
Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Agya/--
VIN: MHKA4DA5N0J005281

Odometer Reading: 107680
License Plate: NF39YPGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (6)

System	Status/DTC
EFI	0
A/B	1
Combination meter	0
Body	0
Electric power steering (EPS)	2
Combination switch	0

DTC (3)

A/B (1 DTC)

DTC	Description	Status
B1806	Passenger seat frontal collision squib circuit open	History

Electric power steering (EPS) (2 DTCs)

DTC	Description	Status
C1552	PIG voltage abnormality	History
C1557	Overheat preventive control current limit history	History

Technician Notes

2017309875

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.