

Honda VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Honda/Ballade/--
VIN: MRHGM2640DP050192

Odometer Reading: 276510km
License Plate: KW40TGGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V10.30

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (4)

System	Status/DTC
Engine-PGM FI	 1
AT	 0
ABS/TCS/VSA	 1
SRS	 3

DTC (5)

Engine-PGM FI (1 DTC)

DTC	Description	Status
P0141	HO2S S2 heater circuit malfunction	Temporary DTC

ABS/TCS/VSA (1 DTC)

DTC	Description	Status
61-11	Modulator-control unit power source circuit (IG) low voltage	Permanent DTC

SRS (3 DTCs)

DTC	Description	Status
85-61	No signal from the ODS unit	Permanent DTC
32-10	Open or increased resistance in the right side airbag inflator	Permanent DTC
31-10	Open in the driver's side airbag inflator	Permanent DTC

Technician Notes

2017304198

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.