

Land Rover VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Land Rover/Evoque (L538)/--
VIN: SALVA2AD3FH044688

Odometer Reading: 138169km
License Plate: DV71NWGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.11

Serial Number: VB8GJCC01509
Repair Order Number: --

 System Scanned (28)

System	Status/DTC
PCM (Powertrain Control Module)	 5
TCM (Transmission Control Module)	 0
ABS (ABS Control Module)	 1
RCM (Restraints Control Module)	 8
IPC (Instrument Cluster Control Module)	 1
PBM (Parking Brake Control Module)	 0
BCM (Body Control Module)	 3
TCCM (Transfer Case Control Module)	 0
GWM (Gateway Module)	 1
HVAC (Heating Ventilation And Air Conditioning Control Module)	 0
SASM (Steering Angle Sensor Module)	 0
DDM (Driver's Door Module)	 0
PDM (Passenger's Door Module)	 0
DSM (Driver's Seat Module)	 2
RGTM (Rear Gate / Trunk Module)	 0
AWDCM (All-wheel Drive Control Module)	 0
GSM (Gear Shift Module)	 0
HCM (Headlamp Control Module)	  0
ATCM (All Terrain Control Module)	 0
PAM (Parking Assist Control Module)	  4

PSCM (Power Steering Control Module)	✓	0
RFA (Keyless Vehicle Module)	✗	3
FCDIM (Front Control/display Interface Module (High Level Display Front))	✓	0
FCIMB (Front Controls Interface Module B (Front Audio Control Panel))	✓	0
IPMB (Image Processing Module B)	ADAS	✗ 1
NAV (Navigation Control Module)	✗	1
AAM (Audio Amplifier Module)	✓	0
ACM (Audio Front Control Module)	✗	1

DTC (31)

PCM (Powertrain Control Module) (5 DTCs)

DTC	Description	Status
U0405-84	Invalid data sent from speed control module	Intermittent
P115A-00	Low fuel level - forced limited power	Intermittent
P115A-68	Low fuel level - forced limited power	Intermittent
P115B-68	Low fuel level - forced engine shutdown	Intermittent
P115B-00	Low fuel level - forced engine shutdown	Intermittent

ABS (ABS Control Module) (1 DTC)

DTC	Description	Status
U0001-82	HS CAN communication bus	Permanent

RCM (Restraints Control Module) (8 DTCs)

DTC	Description	Status
B0001-13	Driver front airbag (stage 1) deployment control	History
B0010-13	Passenger frontal stage 1 deployment control	Permanent
B0002-13	Driver front airbag (stage 2) deployment control	Intermittent
B0011-13	Passenger frontal stage 2 deployment control	Permanent
B1211-13	Driver seatbelt retractor pretensioner deployment control	Permanent
B1214-13	Passenger seatbelt retractor pretensioner deployment control	Permanent
B0004-13	Driver knee bolster deployment control	Permanent
B1193-00	Crash event storage full and locked	Permanent

IPC (Instrument Cluster Control Module) (1 DTC)

DTC	Description	Status
-----	-------------	--------

U0011-87	MS CAN communication bus performance	Intermittent
----------	--------------------------------------	--------------

BCM (Body Control Module) (3 DTCs)

DTC	Description	Status
B102B-87	Passive key	History
B12F6-11	Headlamp power supply A	Permanent
B12F6-15	Headlamp power supply A	Intermittent

GWM (Gateway Module) (1 DTC)

DTC	Description	Status
B1412-96	Quiescent relay box	Permanent

DSM (Driver's Seat Module) (2 DTCs)

DTC	Description	Status
U0011-82	MS CAN communication bus performance	History
U3001-46	Control module improper shutdown	Permanent

PAM (Parking Assist Control Module) (4 DTCs)

DTC	Description	Status
B1B36-14	Right front outer sensor	Permanent
B1B38-14	Right front inner sensor	Permanent
B1B40-14	Left front outer sensor	Permanent
B1B42-14	Left front inner sensor	Permanent

RFA (Keyless Vehicle Module) (3 DTCs)

DTC	Description	Status
B10C4-15	Right rear unlock pull switch	Intermittent
B10CB-13	Right rear door handle antenna	Intermittent
U3000-63	Control module	Intermittent

IPMB (Image Processing Module B) (1 DTC)

DTC	Description	Status
U0140-08	Lost communication with BCM	Intermittent

NAV (Navigation Control Module) (1 DTC)

DTC	Description	Status
U0300-00	Internal control module software incompatibility	Intermittent

ACM (Audio Front Control Module) (1 DTC)

DTC	Description	Status
B1252-19	USB port	Intermittent

Technician Notes

2017304612

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.