Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240220095205
Test Time: 2024-02-20 09:52:05
Technician: Travino

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/CLIO IV/--
VIN: VF15R400E59090389
Odometer Reading: 132402
License Plate: HH58VDGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V12.00
Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(12)

System	Status/DTC
Injection	10
Automatic gearbox	10
ABS	9
Airbag / pretensioners	3
Instrument panel	6
UCH	5
Variable PAS	2
UPC	3
Radio	2
Air conditioning	2
Multimedia interface	1
Hands-free module	4

DTC (57)

Injection (10 DTCs)

DTC	Description	Status
DTC008963	Fuel pressure regulation Time out communication	Memory
DTC020312	Cylinder 3 injector control circuit Short-circuit to +12V	Memory

DTC022516	Pedal potentiometer circuit track 1 Battery voltage too low	Memory
DTC022664	Brake/accelerator pedal positions Incoherence between pedal track 1 and track 2	Memory
DTC0226F1	Brake/accelerator pedal positions Jammed accelerator pedal detected.	Memory
DTC0303F8	Misfire on cylinder 3 Polluting misfiring.	Memory
DTC056016	Computer supply voltage Permanent high level	Memory
DTC059713	Coolant circuit switching solenoid valve Open circuit	Memory
DTC1525F3	Consistent multiplex signals for CC/SL The data supplied to the cruise control or speed limiter are not correct.	Memory
DTCC12187	Multiplexed traction control connection Invalid source computer multiplex signals.	Memory

Automatic gearbox (10 DTCs)

DTC	Description	Status
DTC17431C	Clutch 1 motor circuit	Memory
DTC17441C	Clutch 2 motor circuit	Memory
DTC180516	Computer supply voltage Low voltage	Memory
DTC181516	Battery voltage 12 V Low voltage	Memory
DTC187078	Clutch 2 Clutch position inconsistent	Memory
DTC18981C	Shift drum 1 motor circuit Supply voltage not within tolerance.	Memory
DTC18991C	Shift drum 2 motor circuit Supply voltage not within tolerance.	Memory
DTC191211	Gearbox input 1 speed sensor circuit Short circuit to earth.	Active
DTC191311	Gearbox input 2 speed sensor circuit Short circuit to earth.	Active
DTC500886	External temp. Multiplex signal Signal incoherence.	Memory

ABS (9 DTCs)

DTC	Description	Status
DTC404064	Stop switch information Signal plausibility failure	Memory

DTCC00100	Multiplexed network	Memory
DTCC10100	Auto trans multiplexed emission missing	Memory
DTCC12600	Steering wheel angle sensor multiplex signals	Memory
DTCC15500	Cntrl panel sensor multiplexed emission missing	Memory
DTCC40100	Invalid INJ. Multiplex signals	Memory
DTCC40200	Multiplexed auto trans information invalid	Memory
DTCF00313	Computer power supply Open circuit	Memory
DTCF00316	Computer power supply Circuit voltage below threshold	Memory

Airbag / pretensioners (3 DTCs)

DTC	Description	Status
DTC80D224	Warning light circuit fault Inconsistency between the warning light status transmitted by the instrument panel and the request made by the airbag computer.	Memory
DTCC15587	Instrument panel multiplexed emission absent	Memory
DTCF00316	Computer supply voltage Feed voltage too low	Memory

Instrument panel (6 DTCs)

DTC	Description	Status
DTC94011C	Oil level sensor circuit Battery voltage outside range	Memory
DTC940413	Airbag fault warning light circuit Open circuit	Memory
DTC940811	Seat belt warning light circuit Short circuit to earth.	Memory
DTC941211	External temperature sensor circuit Short circuit to earth.	Memory
DTCC00187	CAN communication Signal missing.	Memory
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory

UCH (5 DTCs)

DTC	Description	Status
DTC952014	Starter relay Open circuit or short circuit to earth	Memory
DTC953018	Left indicator circuit	Memory

DTC953118	Right indicator circuit Circuit current below threshold	Memory
DTC956301	Brake pedal contact circuit	Memory
DTC95A064	Rear screen wiper circuit	Memory

Variable PAS (2 DTCs)

DTC	Description	Status
DTCF00313	Computer power supply Open circuit	Memory
DTCF00316	Computer power supply Low voltage	Memory

UPC (3 DTCs)

DTC	Description	Status
DTC920F81	Upc-alternator link Invalid.	Memory
DTC922211	Steering column lock +APC circuit Short circuit to earth.	Memory
DTC922511	Power supply Short circuit to earth.	Memory

Radio (2 DTCs)

DTC	Description	Status
DTC934262	Unit locked Computer locked	Memory
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory

Air conditioning (2 DTCs)

DTC	Description	Status
DTC910549	Computer Internal electronic fault	Memory
DTCF00316	Computer supply voltage Low voltage	Memory

Multimedia interface (1 DTC)

DTC	Description	Status
DTC930316	Power supply Low voltage	Memory

Hands-free module (4 DTCs)

DTC	Description	Status
DTCA0334A	Dongle	Memory

DTCA05177	Steering lock Control position inaccessible	Memory
DTCA0531C	Steering column lock +APC circuit	Memory
DTCA06004	Wake up signal Internal fault	Memory

Technician Notes

2016274482

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.