

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/LOGAN II/SANDERO II/--
VIN: VF15SRAAC63539692

Odometer Reading: 144480km
License Plate: JK01TDGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
INJ(Injection)	 9
ABS(Anti-lock braking system)	 6
ABG(Airbag / pretensioners)	 4
TDB(Instrument panel)	 4
UCH(Central control unit)	 8
DAV(Variable power assist steering)	 1
RDO(Radio)	 2

AQAS

DTC (34)

INJ(Injection) (9 DTCs)

DTC	Description	Status
DTC001192	Inlet camshaft shifter Phaser control outside of limits.	Active
DTC013012	Upstream oxygen sensor circuit Short-circuit to +12V	Memory
DTC013612	Downstream oxygen sensor circuit Short-circuit to +12V	Memory
DTC017009	Fuel circuit functional fault Component in poor condition.	Memory
DTC022664	Brake/accelerator pedal positions Signal incoherence.	Memory
DTC056016	Computer supply voltage Permanent low level	Memory
DTC064513	Air conditioning compressor control Open circuit	Memory

DTC083362	Clutch switch signal consistency	Memory
DTC226322	Boost pressure circuit Turbocharging pressure is too low.	Active

ABS(Anti-lock braking system) (6 DTCs)

DTC	Description	Status
DTC405155	Steering angle sensor initialization Not configured	Memory
DTCC10000	Injection multiplexed emission missing	Memory
DTCC12600	Steering wheel angle sensor multiplex signals	Memory
DTCC15500	Cntrl panel sensor multiplexed emission missing	Memory
DTCC40100	Invalid INJ. Multiplex signals	Memory
DTCF00316	Computer power supply Circuit voltage below threshold	Memory

ABG(Airbag / pretensioners) (4 DTCs)

DTC	Description	Status
DTC80DF66	Passenger air bag locking status change	Memory
DTC903616	Power supply voltage	Memory
DTC903617	Power supply voltage	Memory
DTCC15587	Instrument panel multiplexed emission absent	Memory

TDB(Instrument panel) (4 DTCs)

DTC	Description	Status
DTC941111	Oil pressure sensor circuit Short circuit to earth.	Memory
DTCC00187	CAN communication Signal missing.	Memory
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory
DTCF00317	Battery voltage 12 V Feed voltage too high	Memory

UCH(Central control unit) (8 DTCs)

DTC	Description	Status
DTC951924	Neutral switch	Memory
DTC953018	Left indicator circuit	Memory
DTC953019	Left indicator circuit	Memory
DTC953118	Right indicator circuit Circuit current below threshold	Memory

DTC953119	Right indicator circuit Circuit current above threshold	Memory
DTC956023	Start of clutch switch travel circuit	Memory
DTC956024	Start of clutch switch travel circuit	Memory
DTC956804	Dongle	Memory

DAV(Variable power assist steering) (1 DTC)

DTC	Description	Status
DTC56075B	ECU memory Internal electronic fault	Memory

RDO(Radio) (2 DTCs)

DTC	Description	Status
DTC934262	Unit locked System jammed	Memory
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory

Technician Notes

2017299616

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.