Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/LOGAN II/SANDERO II/--
VIN: VF15SRAAC64350511

Odometer Reading: 190290km
License Plate: JT75BRGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
INJ(Injection)	4
ABS(Anti-lock braking system)	2
ABG(Airbag / pretensioners)	0
TDB(Instrument panel)	1
UCH(Central control unit)	1
DAV(Variable power assist steering)	1
RDO(Radio)	1

DTC (10)

INJ(Injection) (4 DTCs)

DTC	Description	Status
DTC001192	Inlet camshaft shifter Phaser control outside of limits.	Memory
DTC0226F1	Accelerator pedal position Jammed accelerator pedal detected.	Memory
DTC0302F8	Misfire on cylinder 2 Polluting misfiring.	Memory
DTC0303F8	Misfire on cylinder 3 Polluting misfiring.	Memory

ABS(Anti-lock braking system) (2 DTCs)

DTC	Description	Status
DTC405155	Steering angle sensor initialization Not configured	Memory
DTCF00316	Computer power supply Circuit voltage below threshold	Memory

TDB(Instrument panel) (1 DTC)

DTC	Description	Status
DTCF00316	Battery voltage 12 V Feed voltage too low	Memory

UCH(Central control unit) (1 DTC)

DTC	Description	Status
DTC953118	Right indicator circuit Circuit current below threshold	Memory

DAV(Variable power assist steering) (1 DTC)

DTC	Description	Status
DTC56075B	ECU memory Internal electronic fault	Memory

RDO(Radio) (1 DTC)

DTC	Description	Status
DTC93F016	Battery voltage 12 V Circuit voltage below threshold	Memory

Technician Notes

2017317446

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.