Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261022103822
Test Time: 2026-10-22 10:38:22
Technician: Andrick

Renault VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Renault/LOGAN II/SANDERO II/--
VIN: VF15SRAAC67500916
Odometer Reading: 53123km
License Plate: KG23DFGP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V17.50
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
INJ(Injection)	0
ABS(Anti-lock braking system)	0
ABG(Airbag / pretensioners)	0
TDB(Instrument panel)	0
UCH(Central control unit)	2
DAV(Variable power assist steering)	0
RDO(Radio) ADAS	1

DTC (3)

UCH(Central control unit) (2 DTCs)

DTC	Description	Status
DTC953018	Left indicator circuit	Memory
DTC953118	Right indicator circuit Circuit current below threshold	Memory

RDO(Radio) (1 DTC)

DTC	Description	Status
DTC934749	Bluetooth module Internal electronic failure	Memory

Technician Notes

2017315735

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.