

BMW VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/BMW/3/320i_B48/--
VIN: WBA5F32020FH51696

Odometer Reading: 116779km
License Plate: KJZ464MP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V26.01

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (19)

System		Status/DTC
DME (Engine-Digital Motor Electronics)		 5
EGS (Electronic Transmission Management)		 0
DSC (Dynamic Stability Control)		 0
ACSM (Airbag-Advanced Crash Safety Module)		 0
KOMBI (Instrument Cluster)		 1
BDC (Body Domain Controller)		 4
RVC (Rear View Camera)		 0
ZGM (Central Gateway Module)		 1
PMA (Parking Manoeuvring Assistant)		 2
EPS (Electric Power Steering)		 0
VIP (Virtual integration system)		 2
FLEL (Frontal Light Electronics Left)		 0
FLER (Frontal Light Electronics Right)		 0
FZD (Roof Function Center)		 1
GWS (Gear Selector Switch)		 0
TCB (Combox Emergency Call)		 3
HUB (Headunit Basis)		 0
CON (Controller)		 0
IHKA (Integrated Automatic Heating And A/C System)		 1

DTC (20)

DME (Engine-Digital Motor Electronics) (5 DTCs)

DTC	Description	Status
CD9204	LIN bus, message; radiator blind, lower: missing	Permanent
CD9203	LIN bus, message; radiator blind, top: missing	Permanent
10B105	Information outside temperature sensor, signal: Faulty	Intermittent
10B106	Information outside temperature sensor: Short circuit to B+	Permanent
030E08	Power management: Battery below upper startability limit	Intermittent

KOMBI (Instrument Cluster) (1 DTC)

DTC	Description	Status
B7F655	Instrument panel: Outside temperature sensor Short circuit to B+	Permanent

BDC (Body Domain Controller) (4 DTCs)

DTC	Description	Status
030409	Multifunction steering wheel: Signal implausible	Intermittent
8040D2	PRD status: Activation of parking status, vehicle electrical system not OK	Intermittent
80416D	Engine compartment lid contact switch: Open during driving	Intermittent
804415	Radio remote control: Battery undervoltage	Permanent

ZGM (Central Gateway Module) (1 DTC)

DTC	Description	Status
CD0600	ZGM: Ethernet: Physical fault.	Permanent

PMA (Parking Manoeuvring Assistant) (2 DTCs)

DTC	Description	Status
803207	Ultrasonic sensors: Extraneous noise detected	Intermittent
D4142C	Signal (ambient temperature) invalid, transmitter KOMBI	Permanent

VIP (Virtual integration system) (2 DTCs)

DTC	Description	Status
D7543A	Signal (ambient temperature, 252.1.4) invalid, transmitter KOMBI	Permanent
D75601	Signal (parking surrounding area detection) invalid, transmitter PMA	Intermittent

FZD (Roof Function Center) (1 DTC)

DTC	Description	Status
801A55	Anti-theft alarm system: Alarm signal - details in alarm memory	Intermittent

TCB (Combox Emergency Call) (3 DTCs)

DTC	Description	Status
B7F341	Emergency battery: Hardware faulty	Intermittent
031786	TCB: Functional limitation of Last State Call	Intermittent
031785	TCB: Functional limitation of breakdown call	Permanent

IHKA (Integrated Automatic Heating And A/C System) (1 DTC)

DTC	Description	Status
E71417	Signal (ambient temperature) invalid, transmitter KOMBI	Permanent

Technician Notes
2017303921

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.