

BMW VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/BMW/3'/320i_B48/--
VIN: WBA8A16000NU73894

Odometer Reading: 89041km
License Plate: LCM386NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V26.01

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (15)

System	Status/DTC
DME (Engine-Digital Motor Electronics)	 2
EGS (Electronic Transmission Management)	 0
DSC (Dynamic Stability Control)	 2
ACSM (Airbag-Advanced Crash Safety Module)	 0
KOMBI (Instrument Cluster)	 0
FEM (Front Electronic Module)	 3
ZGM (Central Gateway Module)	 1
ICM (Integrated Chassis Management)	 0
EPS (Electric Power Steering)	 0
GWS (Gear Selector Switch)	 0
TCB (Combox Emergency Call)	 1
HUB (Headunit Basis)	 1
CON (Controller)	 0
REM (Rear Electronic Module)	 4
IHKA (Integrated Automatic Heating And A/C System)	 0

DTC (14)

DME (Engine-Digital Motor Electronics) (2 DTCs)

DTC	Description	Status
213901	Power management: Reduction or shutdown of individual electrical consumer	Intermittent

133710	Intake valves adaptation air mass flow: Lower limit position reached	Intermittent
--------	--	--------------

DSC (Dynamic Stability Control) (2 DTCs)

DTC	Description	Status
480A90	DSC: Roller brake tester mode active	Intermittent
480A12	Brake pad wear sensor: Rear axle, replace brake pads	Permanent

FEM (Front Electronic Module) (3 DTCs)

DTC	Description	Status
8040B7	De-activation of terminal 15: Top startability limit reached	Intermittent
8040B9	De-activation of terminal 30B: Top startability limit reached	Intermittent
8040BD	Reset or deactivation of terminal 30F	Intermittent

ZGM (Central Gateway Module) (1 DTC)

DTC	Description	Status
CD0487	ZGM: Synchronisation process for FlexRay failed	Intermittent

TCB (Combox Emergency Call) (1 DTC)

DTC	Description	Status
B7F318	Emergency call LED, fault	Permanent

HUB (Headunit Basis) (1 DTC)

DTC	Description	Status
B7F8C6	CID: Reduction in brightness due to excess temperature	Intermittent

REM (Rear Electronic Module) (4 DTCs)

DTC	Description	Status
030181	Window regulator, passenger-side door, back: Window regulator on driver's door: relay closing, no output voltage	Intermittent
0301A0	Window regulator on passenger's side door, rear: system is not normalised.	Intermittent
0301B1	Window regulator on passenger's side door, rear: button jamming	Intermittent
804844	Central locking drive, tailgate: line disconnection or short circuit to B+	Intermittent

Technician Notes

2017303554

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.