# Mercedes-Benz VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Mercedes-Benz/C (204)/--
VIN: WDD2040312R306744

Odometer Reading: 239263km
License Plate: CN89JMGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT
Version: V19.33

Serial Number: VB8GJCC01509
Repair Order Number: --

## System Scanned ( 32 )

| System | Status/DTC |
|---|---|
| ECM(Engine Control Unit) | 0 |
| TCM(Transmission Control Unit) | 0 |
| ESP(Electronically controlled vehicle stability braking system control unit) | 4 |
| SRS(Supplemental Restraint System Control Unit) | 0 |
| KI(Instrument Cluster) | 1 |
| PTS(Parking System) ADAS | 1 |
| SAMF(Front SAM signal acquisition control unit) | 0 |
| LIN:AISP(Interior mirror) | 0 |
| LIN:FSW(Wiper Motor) | 0 |
| LIN:OBF(Upper Control Panel) | 0 |
| LIN:VCS(Rain/sunlight sensor) | 0 |
| SAMR(Rear SAM signal acquisition control unit) | 0 |
| LIN:AS(Alarm Siren) | 0 |
| LIN:BSN(Battery Sensor) | 0 |
| LIN:EDW(Interior Protection System Control Unit) | 0 |
| EZS(Electronic Ignition Lock Control Unit) | 0 |
| ES(Electrohydraulic Power Steering) | 2 |
| KLA(Air Conditioner Control Unit) | 1 |
| HU(Head Unit Control Unit) | 0 |
| DSI(Shift Lever Control Unit) | 0 |

| | |
|---|---|
| DMFL(Left Front Door Control Unit) | 1 |
| DMFR(Right Front Door Control Unit) | 3 |
| DMRR(Right Rear Door Control Unit) | 1 |
| DMRL(Left Rear Door Control Unit) | 1 |
| ZBE(Head Unit Display) | 0 |
| ZAN(Center Display Control Unit) | 1 |
| UCI(Media Interface) | 0 |
| RBTMFR(Right Front Seat Belt Tensioner Control Unit) | 0 |
| RBTMFL(Left Front Seat Belt Tensioner Control Unit) | 1 |
| MRM(Steering Column Control Unit) | 0 |
| FSCU(Fuel Pump Control Unit) | 0 |
| CGW(Central Gateway Control Unit) | 0 |

## DTC ( 17 )

### ESP(Electronically controlled vehicle stability braking system control unit) ( 4 DTCs )

| DTC | Description | Status |
|---|---|---|
| C253500 | One or more signals sent from 'CE04 (Central gateway control unit)' via the CAN bus is implausible. | Stored(Event codes) |
| C200200 | The supply voltage of 'CC52 (Electronic stability program control module)' is too high (overvoltage). | Stored(Event codes) |
| C326600 | Consequential fault | Stored(Event codes) |
| C253400 | One or more signals sent from 'CE04 (Central gateway control unit)' via the CAN bus is implausible. | Stored(Event codes) |

### KI(Instrument Cluster) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| U016887 | Communication with the electronic ignition lock has a malfunction. The message is missing. | Stored(Event codes) |

### PTS(Parking System) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| C41500 | Implausible data were received from 'ESP'. | Stored |

### ES(Electrohydraulic Power Steering) ( 2 DTCs )

| DTC | Description | Status |
|---|---|---|
| U041600 | Implausible data were received from 'Traction system'. | Stored(Event codes) |
| P063500 | The electric power steering has a malfunction. | Stored |

## KLA(Air Conditioner Control Unit) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| A10D00 | The power supply is too low. | Stored(Event codes) |

## DMFL(Left Front Door Control Unit) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| A10C17 | The power supply is outside the valid range. The limit value for electrical voltage has been exceeded. | Stored(Event codes) |

## DMFR(Right Front Door Control Unit) ( 3 DTCs )

| DTC | Description | Status |
|---|---|---|
| A10C17 | The power supply is outside the valid range. The limit value for electrical voltage has been exceeded. | Stored |
| C21500 | Communication with the switch group of 'Door' has a malfunction. | Stored |
| 975515 | The output for the ambient lamp has a malfunction. There is a short circuit to positive or an open circuit. | Active and stored |

## DMRR(Right Rear Door Control Unit) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| A10C17 | The power supply is outside the valid range. The limit value for electrical voltage has been exceeded. | Stored |

## DMRL(Left Rear Door Control Unit) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| A10C17 | The power supply is outside the valid range. The limit value for electrical voltage has been exceeded. | Stored |

## ZAN(Center Display Control Unit) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| C155 | Communication with the instrument cluster has a malfunction. | Stored(Event codes) |

## RBTMFL(Left Front Seat Belt Tensioner Control Unit) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| 530900 | 'CB71 (Left front reversible emergency tensioning retractor)' is defective. | Stored |

## Technician Notes

2017326079

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*