Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/EcoSport/--
VIN: WF01XXERK1MM01943

Odometer Reading: 104069
License Plate: KX96RTGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
PCM(Powertrain control module)	1
ABS(Anti-lock brake system)	0
RCM(Restraint control module)	0
IPC(Instrument panel control module)	0
ACM(Audio control module)	0
BdyCM(Body control module) ADAS	2
GWM(Gateway module A)	0
HVAC(Heating ventilation air conditioning)	0
PAM(Parking aid module) ADAS	0
PSCM(Power steering control module)	0
SCCM(Steering column control module)	0

DTC (3)

PCM(Powertrain control module) (1 DTC)

DTC	Description	Status
P0131:00-24	Oxygen Sensor Sensor Circuit Low Voltage (Bank 1 Sensor 1)	CMDTCs

BdyCM(Body control module) (2 DTCs)

DTC	Description	Status
B1218:00-48	Transmitter Identification Code	CMDTCs
B121A:11-48	Keypad Illumination Output	CMDTCs

Technician Notes

2017317291

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.