Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261023154811
Test Time: 2026-10-23 15:48:11
Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/5N - Tiguan 2008 >/--
VIN: WVGZZZ5NZEW009649

Odometer Reading: 298019
License Plate: KR13RNGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (17)

System	Status/DTC
01 - Engine Control Module 1	4
03 - Brakes 1	0
08 - Air conditioning	1
15 - Airbag	1
16 - Steering column electronics	2
17 - Instrument cluster	1
19 - Gateway	0
25 - Immobilizer	0
42 - Driver's door electronics	4
44 - Power steering	0
52 - Passenger's door electronics	1
53 - Parking Brake	1
55 - Headlamp range control ADAS	3
56 - Radio	5
61 - Battery Regulation	1
69 - Trailer Function	2
77 - Telephone	1

DTC (27)

01 - Engine Control Module 1 (4 DTCs)

DTC	Description	Status
P06E900	Engine Starter Performance	Passive/Sporadic

P013500	O2 Sensor Heater Circ.,Bank1-Sensor1 ,Malfunction	Active/static
P086B00	Neutral Position Sensor 'A' Range/Performance	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Passive/Sporadic

08 - Air conditioning (1 DTC)

DTC	Description	Status
B109D71	Air distribution door servomotor ,Actuator stuck	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

16 - Steering column electronics (2 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
B114829	Terminal 15 ,Range/performance	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

42 - Driver's door electronics (4 DTCs)

DTC	Description	Status
B11EC54	Motor for front window regulator ,No basic setting	Active/static
B11F601	Mirror fold-in motor ,Electrical fault	Active/static
B11FD01	Turn signal in exterior rear-view mirror ,Electrical error	Active/static
B122E29	Lock unit for rear central locking ,Range/performance	Passive/Sporadic

52 - Passenger's door electronics (1 DTC)

DTC	Description	Status
B11EC54	Motor for front window regulator ,No basic setting	Active/static

53 - Parking Brake (1 DTC)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

55 - Headlamp range control (3 DTCs)

DTC	Description	Status
C108116	Left headlamp power output stage ,Voltage too low	Passive/Sporadic
C108216	Right headlamp power output stage ,Voltage too low	Passive/Sporadic
C108000	Left-/right hand driving switch-over active	Active/static

56 - Radio (5 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00874:011	Left front treble speaker - Open circuit	Active/static
00875:011	Right front treble speaker - Open circuit	Active/static
00856:011	Antenna, on radio - Open circuit	Active/static

61 - Battery Regulation (1 DTC)

DTC	Description	Status
01598:003	Drive battery voltage - mechanical malfunction	Passive/Sporadic

69 - Trailer Function (2 DTCs)

DTC	Description	Status
02563:010	Bulb for right tail light on trailer - Open circuit/short circuit to B+	Active/static
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

77 - Telephone (1 DTC)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic

Technician Notes

2017316480

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.