

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AW/C1 - T-Cross 2019 >/--
VIN: WVGZZZC1ZLY100332

Odometer Reading: 180690km
License Plate: JM78FJGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V24.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (16)

System	Status/DTC
01 - Engine Control Module 1	 19
02 - Transmission electronics	 3
03 - Brakes 1	 2
08 - Air conditioning	 2
09 - Electronic central electric	 3
15 - Airbag	 1
17 - Instrument cluster	 2
19 - Gateway	 3
2B - Steering Column Locking	 1
44 - Power steering	 2
55 - Headlamp range control	 2
5F - Information electronics 1	 2
76 - Parking aid	 1
B7 - Interface for access/start system	 2
D6 - Light control left 2	 1
D7 - Light control right 2	 2

DTC (48)

01 - Engine Control Module 1 (19 DTCs)

DTC	Description	Status
P06E900	Engine Starter Performance	Active/static
U350100	Control Module Input Power 'A' Circuit Low	Passive/Sporadic

U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
P029900	Turbocharger/supercharger underboost	Passive/Sporadic
P253200	Ignition Switch Run Position Circuit High	Passive/Sporadic
U140A00	Terminal 30 Open circuit	Passive/Sporadic
P308100	Engine temperature too low	Passive/Sporadic
P168000	Reset-resistant limp-home	Passive/Sporadic
P001100	A Camshaft Position (Bank1) Timing over-advanced or System Performance	Passive/Sporadic
P102000	Fuel Pressure Regulation Control limit exceeded	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P014100	O2 Sensor Heater Circ.,Bank1-Sensor2 Malfunction	Passive/Sporadic
P030000	Random Misfire Detected No Sub Type Information	Passive/Sporadic
P030100	Cylinder 1 Misfire Detected No Sub Type Information	Passive/Sporadic
P030200	Cylinder 2 Misfire Detected No Sub Type Information	Passive/Sporadic
P030300	Cylinder 3 Misfire Detected No Sub Type Information	Passive/Sporadic
P130A00	Cylinder suppression	Passive/Sporadic
P157000	Engine control unit disabled	Passive/Sporadic
P125000	Fuel level too low	Passive/Sporadic

02 - Transmission electronics (3 DTCs)

DTC	Description	Status
P278700	Clutch temperature too high	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic
P060700	Control Module Performance	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
C106A16	ABS valves voltage supply Voltage too low	Passive/Sporadic

U140000	Function restriction due to low voltage	Passive/Sporadic
---------	--	------------------

08 - Air conditioning (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
B109211	Recirculation flap motor Circuit short to ground	Passive/Sporadic

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B147918	Remote control vehicle key 1 Insufficient current	Active/static
U112300	Databus error value received	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B1302F0	Electronic steering column lock control module not authorized	Passive/Sporadic

19 - Gateway (3 DTCs)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic

2B - Steering Column Locking (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

44 - Power steering (2 DTCs)

DTC	Description	Status
U140A00	Terminal 30 Open circuit	Passive/Sporadic
B200FF0	Internal malfunction	Passive/Sporadic

55 - Headlamp range control (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

5F - Information electronics 1 (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
B105113	Telephone baseplate Open circuit	Passive/Sporadic

76 - Parking aid (1 DTC)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic

B7 - Interface for access/start system (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

D6 - Light control left 2 (1 DTC)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic

D7 - Light control right 2 (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
C11A413	Turn signal bulb Open circuit	Active/static

Technician Notes
2017253236

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.