Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AW/C1 - T-Cross 2019 >/--
VIN: WVGZZZC1ZMY093066

Odometer Reading: 79666km
License Plate: JY81TCGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (15)

System	Status/DTC
01 - Engine Control Module 1	3
02 - Transmission electronics	1
03 - Brakes 1	3
08 - Air conditioning	3
09 - Electronic central electric	1
15 - Airbag	1
17 - Instrument cluster	3
19 - Gateway	3
44 - Power steering	2
55 - Headlamp range control ADAS	2
5F - Information electronics 1	3
69 - Trailer Function	2
76 - Parking aid ADAS	2
D6 - Light control left 2	1
D7 - Light control right 2	1

DTC (31)

01 - Engine Control Module 1 (3 DTCs)

DTC	Description	Status
U350100	Control Module Input Power 'A' Circuit Low	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic

P168000	Reset-resistant limp-home	Passive/Sporadic

02 - Transmission electronics (1 DTC)

DTC	Description	Status
P056200	System Voltage ,Low Voltage	Passive/Sporadic

03 - Brakes 1 (3 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
B13BCF2	Multiple collision brake ,No function	Passive/Sporadic
C106A16	ABS valves voltage supply ,Voltage too low	Passive/Sporadic

08 - Air conditioning (3 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake ,No function	Passive/Sporadic

17 - Instrument cluster (3 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U111000	Function restriction due to communication interruption	Passive/Sporadic
B104C29	Key ,Range/performance	Passive/Sporadic

19 - Gateway (3 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140600	Static current ,too high	Passive/Sporadic
B1802F1	NV-Energy management ,Alarm triggered	Passive/Sporadic

44 - Power steering (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B200FF0	Internal malfunction	Passive/Sporadic

55 - Headlamp range control (2 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

5F - Information electronics 1 (3 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B10CD00	Function restriction caused by energy management	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic

69 - Trailer Function (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
B200044	Control module faulty ,Data storage malfunction	Passive/Sporadic

76 - Parking aid (2 DTCs)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic

D6 - Light control left 2 (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

D7 - Light control right 2 (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

Technician Notes

2017311215

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.