

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AW/C1 - T-Cross 2019 >/--
VIN: WVGZZZC1ZPY017527

Odometer Reading: 90567km
License Plate: KVV783NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (14)

System	Status/DTC
01 - Engine Control Module 1	 9
02 - Transmission electronics	 2
03 - Brakes 1	 0
08 - Air conditioning	 2
09 - Electronic central electric	 1
15 - Airbag	 1
17 - Instrument cluster	 2
19 - Gateway	 2
44 - Power steering	 1
55 - Headlamp range control	 2
5F - Information electronics 1	 3
76 - Parking aid	 2
D6 - Light control left 2	 1
D7 - Light control right 2	 1

DTC (29)

01 - Engine Control Module 1 (9 DTCs)

DTC	Description	Status
P194600	Coolant fan control module 1 Faulty/open circuit in voltage supply	Passive/Sporadic
U350100	Control Module Input Power 'A' Circuit Low	Passive/Sporadic
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic

U021200	Lost communication with steering column control unit	Passive/Sporadic
U140A00	Terminal 30 Open circuit	Passive/Sporadic
P011800	Coolant temperature sensor 1 Circuit high	Passive/Sporadic
P168000	Reset-resistant limp-home	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P014100	O2 Sensor Heater Circ.,Bank1-Sensor2 Malfunction	Passive/Sporadic

02 - Transmission electronics (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
P056200	System Voltage Low Voltage	Passive/Sporadic

08 - Air conditioning (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
B10CD00	Function restriction caused by energy management	Passive/Sporadic

09 - Electronic central electric (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B104B31	Key No signal	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
-----	-------------	--------

U101100	Supply voltage Voltage too low	Passive/Sporadic
B1802F1	NV-Energy management Alarm triggered	Passive/Sporadic

44 - Power steering (1 DTC)

DTC	Description	Status
B200FF0	Internal malfunction	Passive/Sporadic

55 - Headlamp range control (2 DTCs)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

5F - Information electronics 1 (3 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
B10CD00	Function restriction caused by energy management	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic

76 - Parking aid (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic

D6 - Light control left 2 (1 DTC)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic

D7 - Light control right 2 (1 DTC)

DTC	Description	Status
U140000	Function restriction due to low voltage	Passive/Sporadic

Technician Notes

2017303559

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.