

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/63 - Polo Ameo 2017 >/--
VIN: WVVZZZ60ZLT072578

Odometer Reading: 197021
License Plate: MT44KPGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (10)

System	Status/DTC
01 - Engine Control Module 1	 7
03 - Brakes 1	 0
04 - Steering Angle Sender	 1
09 - Electronic central electric	 2
15 - Airbag	 2
17 - Instrument cluster	 2
19 - Gateway	 2
25 - Immobilizer	 1
44 - Power steering	 2
56 - Radio	 2

DTC (21)

01 - Engine Control Module 1 (7 DTCs)

DTC	Description	Status
29094:000	Invalid Data Received From Body Control Module	Passive/Sporadic
28823:000	Lost Communication With Restraints Control Module	Passive/Sporadic
28793:000	Lost Communication With Anti-Lock Brake System (ABS) Control Module	Passive/Sporadic
16685:000	Cyl.1 Misfire Detected	Passive/Sporadic
16684:000	Random/Multiple Cylinder Misfire Detected	Passive/Sporadic
28827:000	Lost Communication With Instrument Panel Cluster (IPC) Control Module	Passive/Sporadic

18353:000	Coolant Fan Control (FC) Control Module 1, fan activation Short circuit	Passive/Sporadic
-----------	--	------------------

04 - Steering Angle Sender (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

15 - Airbag (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
U140000	Function restriction due to low voltage	Passive/Sporadic

17 - Instrument cluster (2 DTCs)

DTC	Description	Status
U111100	Function restriction caused by missing message	Passive/Sporadic
U101100	Supply voltage Voltage too low	Passive/Sporadic

19 - Gateway (2 DTCs)

DTC	Description	Status
00778:004	Steering angle sensor - No signal/communication	Passive/Sporadic
01321:004	Airbag control module - No signal/communication	Passive/Sporadic

25 - Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

44 - Power steering (2 DTCs)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic
P332500	Voltage supply Kl.15 implausible	Passive/Sporadic

56 - Radio (2 DTCs)

DTC	Description	Status
-----	-------------	--------

00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

Technician Notes
2017302493

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.