Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/AU/BE/BX - Golf 2013 USA/CAN >/--
VIN: WVWZZZAUZHW332609

Odometer Reading: 93591km
License Plate: JR15JWGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (21)

System	Status/DTC
01 - Engine Control Module 1	5
02 - Transmission electronics	0
03 - Brakes 1	1
08 - Air conditioning	0
09 - Electronic central electric	3
15 - Airbag	0
16 - Steering column electronics	0
17 - Instrument cluster	0
19 - Gateway	1
20 - High beam assistant	0
29 - Left light control	1
39 - Light Control Right	1
42 - Driver's door electronics	1
44 - Power steering	0
4B - Multi-function module	0
52 - Passenger's door electronics	2
5F - Information electronics 1	1
76 - Parking aid ADAS	0
A9 - Structure-Borne Sound Actuator	1
D6 - Light control left 2	8

D7 - Light control right 2 8

DTC (33)

01 - Engine Control Module 1 (5 DTCs)

DTC	Description	Status
P130A00	Cylinder suppression	Passive/Sporadic
P008900	Fuel Pressure Regulator 'A' Performance	Passive/Sporadic
U112300	Databus error value received	Passive/Sporadic
P125000	Fuel level ,too low	Passive/Sporadic
P030100	Cylinder 1 Misfire Detected ,No Sub Type Information	Passive/Sporadic

03 - Brakes 1 (1 DTC)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Passive/Sporadic

09 - Electronic central electric (3 DTCs)

DTC	Description	Status
B12CA15	License plate lamp ,Open circuit/short circuit to B+	Active/static
B12C015	Left tail lamp bulb 2 ,Open circuit/short circuit to B+	Active/static
B12C115	Right tail lamp bulb 2 ,Open circuit/short circuit to B+	Active/static

19 - Gateway (1 DTC)

DTC	Description	Status
B130E00	Rest recommended - function limited	Passive/Sporadic

29 - Left light control (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

39 - Light Control Right (1 DTC)

DTC	Description	Status
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

42 - Driver's door electronics (1 DTC)

DTC	Description	Status
B122D29	Locking unit for central locking ,Range/performance	Active/static

52 - Passenger's door electronics (2 DTCs)

DTC	Description	Status
B177501	Door warning light / entry light ,Electrical error	Active/static
B132202	Passenger side rear window regulator motor ,Signal fault	Passive/Sporadic

5F - Information electronics 1 (1 DTC)

DTC	Description	Status
B106713	Right rear bass speaker ,Open circuit	Active/static

A9 - Structure-Borne Sound Actuator (1 DTC)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic

D6 - Light control left 2 (8 DTCs)

DTC	Description	Status
C1199F6	Hi beam light bulb ,Overtemperature protection active	Passive/Sporadic
C1198F6	Low beam light bulb ,Overtemperature protection active	Passive/Sporadic
C11FD13	Supply for low beam ,Open circuit	Passive/Sporadic
C119AF6	Stationary cornering lamp ,Overtemperature protection active	Passive/Sporadic
U120000	Data bus ,Faulty	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic
C119829	Low beam lamp bulb ,Range/performance	Passive/Sporadic
U120100	Data bus ,No communication	Passive/Sporadic

D7 - Light control right 2 (8 DTCs)

DTC	Description	Status
C1198F6	Low beam light bulb ,Overtemperature protection active	Passive/Sporadic
C119AF6	Stationary cornering lamp ,Overtemperature protection active	Passive/Sporadic
C1199F6	Hi beam light bulb ,Overtemperature protection active	Passive/Sporadic
U120000	Data bus ,Faulty	Passive/Sporadic
U140000	Function restriction ,due to low voltage	Passive/Sporadic
C119829	Low beam lamp bulb ,Range/performance	Passive/Sporadic
U120100	Data bus ,No communication	Passive/Sporadic
C11FD13	Supply for low beam ,Open circuit	Passive/Sporadic

Technician Notes

2017311222

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.