Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/D2 - Virtus 2022 >/--
VIN: WVWZZZD2ZRT015215

Odometer Reading: 125475km
License Plate: MK20RJGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (8)

System	Status/DTC
01 - Engine Control Module 1	8
03 - Brakes 1	0
08 - Air conditioning	0
09 - Electronic central electric	2
15 - Airbag	1
17 - Instrument cluster	1
19 - Gateway	0
44 - Power steering	0

DTC (12)

01 - Engine Control Module 1 (8 DTCs)

DTC	Description	Status
U041600	Invalid data received from vehicle dynamics control module	Passive/Sporadic
U111300	Function limitation due to received malfunction value	Passive/Sporadic
U101700	ABS Control Module ,Check event memory	Passive/Sporadic
U015500	Lost communication with instrument cluster control unit	Passive/Sporadic
P1D7500	Catalyst-damaging combustion misfire detected	Passive/Sporadic
P1D7400	Catalyst-damaging combustion misfire active	Passive/Sporadic
P030200	Cylinder 2 Misfire Detected ,No Sub Type Information	Passive/Sporadic
P157000	Engine control unit disabled	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
B149C01	Left LED headlamp power module ,Electrical fault	Active/static

B149B01	Right LED headlamp power output stage ,Electrical fault	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake ,No function	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
B104C29	Key ,Range/performance	Passive/Sporadic

Technician Notes

2017316062

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.