DEKRA

CONDITION REPORT

Report No:
2017311535
DATE
14/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	14/10/2026		
Inspection Date	14/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	MAZDA	Registration Number	JTP238MP
Model	MAZDA3 1.6 DYNAMIC 5-DR AT [2016-2019]	Register Number	
VIN	JM6BN24Z5J0188397	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/09/2026
Color	RED	Power / Displacement	
Year Model	2017	Paint Finish	M - METALLIC
Km Reading	190,435 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397

DEKRA

CONDITION REPORT

Report No: 2017311535
DATE 14/10/2026





Damage	Repair Way
Side Mirror Left Paintwork • Scratched	Repair
Front Bumper Paintwork • Chipmarks	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Sealing / Rubber Rear Door Left Defective	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Service Brake Performance Front Axle Left / Right Difference out of legal range	Repair
Stabilizer Mounting Front Left Damaged	Replace
Stabilizer Mounting Front Right Damaged	Replace
Control Arm Bush(es) Front Axle Left Damaged	Replace
Control Arm Bush(es) Front Axle Right Damaged	Replace
CV Joint(s) Boot(s) Front Left (inner/outer) Defective	Repair
Dipstick damage	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	1.7	3.1	-	
Rear	1.9	1.6	-	
Emergency / Parking	1.3	1.1	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/55R16	91V	Rapid	Eco809	V	1124	2 mm
Front Right	205/55R16	91V	Rapid	Eco809	V	1124	2 mm
Rear Left	205/55R16	91V	Rapid	Eco809	V	1124	3 mm
Rear Right	205/55R16	91V	Rapid	Eco809	V	1124	3 mm
Spare	T125/70D16	96M	Dunlop	Temporary	V	0000	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397

DEKRA

CONDITION REPORT

Report No:
2017311535
DATE
14/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CMDTCS	U3003:16-08	BATTERY VOLTAGE	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397

DEKRA

CONDITION REPORT


Report No:
2017311535
DATE
14/10/2026


FRONT RIGHT CORNER


REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR


90 DEGREE RIGHT


90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397

DEKRA

CONDITION REPORT

Report No:
2017311535
DATE
14/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397

DEKRA

CONDITION REPORT

Report No:
2017311535
DATE
14/10/2026



ENGINE 1



ENGINE 2




CHASSIS



Coolant bottle



Oil cap



LF TYRE TREAD


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397


DEKRA

CONDITION REPORT

Report No:
2017311535
DATE
14/10/2026



RF TYRE TREAD




LR TYRE TREAD




RR TYRE TREAD



Spare wheel



Shock and brake report



Diagnostic Report page 1


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397

DEKRA

CONDITION REPORT

Report No:
2017311535
DATE
14/10/2026




Diagnostic Report page 2



Water level



Windscreen



Service Brake Performance Front Axle



Sealing / Rubber Rear Door Left



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397

DEKRA

CONDITION REPORT

Report No:
2017311535
DATE
14/10/2026



Door Rear Right



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397

DEKRA

CONDITION REPORT

Report No:
2017311535
DATE
14/10/2026



Bonnet



Front Fender Left




Side Mirror Left



Door Front Left



Door Rear Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397


DEKRA

CONDITION REPORT

Report No:
2017311535
DATE
14/10/2026



Rear bumper



Rear bumper



Boot Lid / Hatch door



CV Joint(s) Boot(s) Front Left (inner/outer)



Stabilizer Mounting Front Left



Stabilizer Mounting Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397

DEKRA

CONDITION REPORT

Report No:
2017311535
DATE
14/10/2026



Control Arm Bush(es) Front Axle Left



Control Arm Bush(es) Front Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JM6BN24Z5J0188397