CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	TOYOTA	Registration Number	KW81FXGP
Model	RUMION 1.5 SX MPV [2021-2023]	Register Number	JPY559L
VIN	JTDDND22S00528205	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2022	Paint Finish	TWO COAT UNI
Km Reading	147,224 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Air Conditioner Insufficient	Replace
Seat Front Left Dirty	Repair
Seat Rear Dirty	Repair
Seat Rear (2. Row) Damaged	Repair
Door Panel Front Right Damaged	Repair
Front Bumper Damaged	Repair
Bonnet Dented	Repair
Front Fender Left Dented	Repair
Rear Fender Right Damaged	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Dented	Repair
Boot Lid / Hatch Door Rubbers Damaged	Replace
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Damaged	Repair
Roof Damaged	Replace
Sub Frame Dented	Repair
Belly plates Damaged	Replace
Gearbox Oil Sweat	Repair
Fuel Tank Dented	Repair
Triangle Missing	Replace
Rear left chassis leg extension damaged	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.13	2.17	-	
Rear	1.79	2.05	-	
Emergency / Parking	1.04	0.72	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	88H	Aplus	A609	V	4924	2 mm
Front Right	185/65 R15	88H	Aplus	A609	V	3125	2 mm
Rear Left	185/65 R15	92T	Barum	Brillantis	V	0222	1 mm
Rear Right	185/65 R15	88H	Encore	Reflex	V	2825	5 mm
Spare	185/65 R15	88H	Bridgestone	Ecopia	V	0000	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE LEFT



90 DEGREE RIGHT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026



ODOMETER



DASHBOARD (W/ ENGINE RUNNING)



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



RF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026



RR TYRE TREAD



LF TYRE TREAD



Spare wheel



Front chassis



Rear chassis



Rear left chassis leg extensio

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026



Spare wheel Accessories



Oil cap and dipstick




ENGINE 1



VIN PLATE OR STICKER



LICENSE DISC



SHOCK AND BRAKE REPORT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026



DIAGNOSTIC REPORT




Door Panel Front Right



Door Front Right



Door Rear Right



Rear Fender Right



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026



Rear bumper



Rear bumper



Boot Lid / Hatch Door Rubbers



Door Rear Left



Door Rear Left



Seat Rear (2. Row)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026



Seat Rear (2. Row)



Front Fender Left



Door Front Left



Door Front Left



Seat Front Left



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026



Bonnet



Bonnet



Air Conditioner



Boot Lid / Hatch door



Sill Panel Left



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026



Front Bumper



Front Bumper



Belly plates



Belly plates



Engine



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205

DEKRA

CONDITION REPORT

Report No:
2017315649
DATE
22/10/2026



Sub Frame



Sub Frame



Fuel Tank



Water level



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00528205