CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	09/10/2026		
Inspection Date	09/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	TOYOTA	Registration Number	LV78XSGP
Model	RUMION 1.5 TX MPV [2023-2025]	Register Number	
VIN	JTDDND22S00631742	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2027
Color	SILVER	Power / Displacement	
Year Model	2023	Paint Finish	TWO COAT UNI
Km Reading	203,472 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Radiator Defective	Repair
Central Air Vent Damaged	Replace
Center Console / Cubbyhole + Lid Damaged	Repair
Tail Light Left Cracked	Replace
Tail Light Right Cracked	Replace
Fog Light Front Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Damaged	Repair
Seat Rear Damaged	Repair
Hood Lining Dirty	Repair
Side Mirror Right Residual Traces of Repair	Repair
Front Bumper Damaged	Replace
Grill Damaged	Replace
Bonnet Residual Traces of Repair	Replace
Bonnet slam plate (Shock tower/ Inner tray) Damaged	Repair
Front Fender Left Residual Traces of Repair	Replace
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Front Fender Left / Inner Tray Damaged	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Boot Lid / Hatch door Damaged	Replace
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Residual Traces of Repair	Repair
Roof Dented	Repair
Windscreen Cracked	Replace
Brake disc 1. Axle left Excessive Wear & Tear	Replace
Brake disc 1. Axle right Excessive Wear & Tear	Replace
Shock Absorber Rear Right Leak	Replace
Tyre Front Left Damaged	Replace
Tyre Rear Left Damaged	Replace
Tyre Rear Right Damaged	Replace
Spare Tyre Worn	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Right Scratched	Repair
Main Beam Left Welded	Repair
Main Beam Right Damaged	Repair
Gearbox Mountings Damaged	Repair
Gearbox Welded	Repair
Fuel Tank Dented	Repair
CV Joint(s) Boot(s) Front Left (inner/outer) Damaged	Replace
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Clutch Operation Insufficient	Repair
Interior boot lock plastic trim damaged	Replace
Rear left and right tyres regrooved	Replace
Fan Cowley damaged	Replace

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No: 2017309907
DATE 09/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.59	2.77	-	
Rear	2.06	2.42	-	
Emergency / Parking	1.79	2.39	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65 R15	88H	Annaite	AN606	V	4225	1 mm
Front Right	185/65 R15	88H	Annaite	AN600	V	4225	2 mm
Rear Left	185/65 R15	88H	Goodyear	Efficient	V	3824	0 mm
Rear Right	185/65 R15	88H	Apollo	Alnac	V	2621	0 mm
Spare	185/65 R15	88H	Teraflex	Ecorun	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Radiator and Aircon condenser strapped with cable ties.
Interior: Vehicle interior dirty and panels scratched.Driver's seat adjuster handle damaged.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Signs of impact damage to front of vehicle.
Undercarriage: Vehicle undercarriage dirty
Road Test: Gear selection faulty.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



Brake and shock absorber repor



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



ODOMETER



Manual Transmission



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT


Report No:
2017309907
DATE
09/10/2026




LF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Spare wheel Accessories



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



LICENSE DISC




VIN PLATE OR STICKER




ENGINE 1



Front chassis



Rear chassis



Fan Cowley

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



Oil cap and dipstick



Interior boot lock plastic tri



Central Air Vent



Seat Rear



Rim Rear Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742


DEKRA

CONDITION REPORT


Report No:
2017309907
DATE
09/10/2026



Door Rear Right



Door Front Right



Front Fender Right



Side Mirror Right



Rim Front Right



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



Windscreen



Front Fender Left



Tyre Front Left



Rim Front Left



Door Front Left



Door Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



Rear Fender Left



Seat Front Left



Center Console / Cubbyhole + Lid



Rear bumper



Rear bumper



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



Roof



Inner Boot Floor Pan and Spare Wheel Well



Hood Lining



Tail Light Left



Tail Light Right



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



Headlight Left




Front Fender Left / Inner Tray



Bonnet slam plate (Shock tower/ Inner tray)



Bonnet slam plate (Shock tower/ Inner tray)



Gearbox



Gearbox Mountings

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



Radiator



Sill Panel Right



Front Bumper



Front Bumper



Grill



Fog Light Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



Main Beam Left



Front Fender Left / Inner Tray



Brake disc 1. Axle left



Sill Panel Left



Sill Panel Left



CV Joint(s) Boot(s) Front Left (inner/outer)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



CV Joint(s) Boot(s) Front Right (inner/outer)




CV Joint(s) Boot(s) Front Right (inner/outer)



Gearbox



Main Beam Left



Brake disc 1. Axle right



Engine

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742


DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



Tyre Rear Right



Tyre Rear Left



Spare Tyre



Shock Absorber Rear Right



Main Beam Right



Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742

DEKRA

CONDITION REPORT

Report No:
2017309907
DATE
09/10/2026



Fuel Tank



Water level



Water level



Seat Front Right



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDDND22S00631742