DEKRA

CONDITION REPORT

Report No:
2017316618
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	TOYOTA	Registration Number	N/A
Model	STARLET 1.5 XI 5-DR [2022-2025]	Register Number	
VIN	JTDJWCA3S00880301	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2025	Paint Finish	M - METALLIC
Km Reading	153,970 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301

DEKRA

CONDITION REPORT

Report No:
2017316618
DATE
26/10/2026





Damage	Repair Way
Bonnet stay and shocks Missing	Replace
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Dented	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Damaged	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Windscreen Cracked	Replace
Tyre Front Left Smooth	Replace
Tyre Front Right Damaged	Replace
Spare Tyre Damaged	Repair
Bolt(s) / Nut(s) Rear Wheel Left Missing	Replace
Bolt(s) / Nut(s) Rear Wheel Right Missing	Replace
Belly plates Damaged	Repair
Radiator Cradle Dented	Repair
No license disc	Replace
Both number plates missing	Replace
ABS light and traction control light on	Repair
Extra spare wheel in side boot	Repair
All four tires deferred sizes	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.1	2.5	-	
Rear	1.6	1.4	-	
Emergency / Parking	1.1	0.9	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301

DEKRA

CONDITION REPORT

Report No:
2017316618
DATE
26/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/50R15	82V	Dunlop	Sp sport	V	2724	0 mm
Front Right	185/60R15	92H	Dunlop	Sp sport	V	1223	0 mm
Rear Left	185/65R15	92T	Sumitomo	Bc10	V	3221	1 mm
Rear Right	T135/70R15	99M	Jk tyre	Temporary	V	2125	3 mm
2 Rear Left In	185/60R15	84H	Continental	Contact	V	0000	0 mm
Spare	T135/70R15	99M	Jk tyre	Temporary	V	4024	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	PENDING	P0420	CATALYST SYSTEM EFFICIENCY BELOW THRESHOLD BANK 1	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF SPRAY WORK DONE ON SOME BODY PANELS

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301

DEKRA

CONDITION REPORT

Report No:
2017316618
DATE
26/10/2026




FRONT RIGHT CORNER



REAR LEFT CORNER




90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301

DEKRA

CONDITION REPORT

Report No:
2017316618
DATE
26/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual




DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



NO LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301

DEKRA

CONDITION REPORT

Report No:
2017316618
DATE
26/10/2026



ENGINE 1



ENGINE 2




CHASSIS



Oil cap and dipstick



Coolant bottle



LF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301

DEKRA

CONDITION REPORT

Report No:
2017316618
DATE
26/10/2026



RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



Spare wheel



Shock and brake report



Diagnostic Report page 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301


DEKRA

CONDITION REPORT


Report No:
2017316618
DATE
26/10/2026




Diagnostic Report page 2



Water level



Bonnet stay and shocks



Windscreen



Spare Tyre



Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301

DEKRA

CONDITION REPORT

Report No:
2017316618
DATE
26/10/2026



Rear Fender Right




Door Rear Right



Door Front Right



Side Mirror Right



Front Fender Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301

DEKRA

CONDITION REPORT

Report No:
2017316618
DATE
26/10/2026



Front Fender Left



Side Mirror Left




Door Front Left



Door Rear Left



Rear Fender Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301

DEKRA

CONDITION REPORT

Report No:
2017316618
DATE
26/10/2026



Rear bumper




Boot Lid / Hatch door



Bolt(s) / Nut(s) Rear Wheel Right



Bolt(s) / Nut(s) Rear Wheel Left



Tyre Front Right



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301


DEKRA

CONDITION REPORT

Report No:
2017316618
DATE
26/10/2026



Inner Boot Floor Pan and Spare Wheel Well



Belly plates



Radiator Cradle



Radiator Cradle



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: JTDJWCA3S00880301