DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	27/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	JN07ZYGP
Model	ACCENT 1.6 FLUID INFOTAINMENT AT [2018-2019]	Register Number	
		Date Of First Licensing	
VIN	KMHCT41DLKU480774	Last COR	
Engine Number		License Expiry Date	31/08/2026
Doors	4	Power / Displacement	
Color	GREY	Paint Finish	TWO COAT METALLIC
Year Model	2020	Fuel	PETROL
Km Reading	561,578 KM	Transmission	MANUAL
Cab / Body Type	SEDAN		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774

DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026





Damage	Repair Way
Engine Wiring Damaged	Replace
Air conditioner pump Defective	Repair
Alternator Defective	Repair
Central Air Vent Damaged	Replace
Radio/CD/USB Missing	Replace
Engine Management Lights Set	Replace
Windscreen Wiper Damaged	Replace
Tail Light Left Damaged	Replace
Tail Light Right Damaged	Replace
Headlight Left Damaged	Replace
Headlight Right Damaged	Replace
Seat Front Left Worn	Repair
Seat Front Right Worn	Repair
Seat Rear Damaged	Repair
Door Panel Front Right Damaged	Replace
Carpet Front Damaged	Replace
Front Bumper Damaged	Repair
Bonnet Damaged	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Door Front Left Damaged	Repair
Door Front Right Damaged	Replace
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Damaged	Replace
Rear bumper Damaged	Repair
Roof Damaged	Repair
Windscreen Damaged	Replace
Control Arm(s) Front Axle Right Damaged	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Worn	Replace
Tyre Rear Left Worn	Replace
Tyre Rear Right Worn	Replace
Rim Front Left Damaged	Replace
Main Beam Left Damaged	Repair
Main Beam Right Damaged	Repair
Sub Frame Damaged	Replace
Gearbox Oil Leak	Repair
Fuel Tank Damaged	Replace
Radiator Cross Member Damaged	Replace
Engine Performance Insufficient	Repair
Engine Noise Idling / Hunting	Repair
Gear Selections Malfunction	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774

DEKRA

CONDITION REPORT

Report No: 2017317189
DATE 27/10/2026

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.7	2.75	-	
Rear	2.35	2.47	-	
Emergency / Parking	1.44	1.63	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/70R14	84T	Cachland	Radial	V	1922	0 mm
Front Right	175/70R14	84H	Windforce	Radial	V	1425	0 mm
Rear Left	175/70R14	84H	Windforce	Radial	V	1125	0 mm
Rear Right	175/70R14	84H	Windforce	Radial	V	1425	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AB	B1346	DRIVER AIRBAG (DAB) RESISTANCE TOO HIGH (1ST STAGE)	ACTIVE

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: aircon pump bypass with fan belt. alternator incorrectly fitted.
Electrical Components and Instruments: vehicle struggles to start.
Lights: Battery loose.
Body • Exterior: Minor dents and scratches and stone chips to body panels. Signs of repair work done to body panels. Poor alignment to somebody panels. Signs of hail damage to some body panels. Repair work done to vehicle below standard. Vehicle body in poor condition. wiper villainster damaged.
Undercarriage: Signs of impact damage to front of vehicle.
Road Test: to engaged first gear you need to lift up the reverse lockout and carefully put it between first and reverse position to engage first gear.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Werner Laubscher

This document was created electronically and is valid without signature.

General Remarks:

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774

DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026

The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774


DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026



Brake test.



Diagnostic.



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774


DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026



ODOMETER


Manual.



90 DEGREE FRONT


90 DEGREE RIGHT



90 DEGREE REAR


90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774


DEKRA

CONDITION REPORT


Report No:
2017317189
DATE
27/10/2026




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774

DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026



ENGINE 1



Undercarriage front.



Undercarriage rear.



Oil cap and dipstick.



Water level



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774

DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026



Front Bumper



Bonnet




Front Fender Left



Door Front Left



Door Rear Left



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774

DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026



Rear bumper



Rear bumper



Door Front Right



Door Rear Right



Front Fender Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774

DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026



Roof




Boot Lid / Hatch door



Windscreen



Air conditioner pump



Alternator



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774


DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026



Headlight Left



Tyre Rear Left



Tyre Rear Right



Tyre Front Left



Tyre Front Right



Control Arm(s) Front Axle Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774

DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026




Sub Frame



Main Beam Right



Main Beam Left



Radiator Cross Member



Fuel Tank



Gearbox

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774

DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026



Rim Front Left



Engine Wiring



Tail Light Left



Tail Light Right



Windscreen Wiper



Seat Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774

DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026




Seat Front Left



Carpet Front



Seat Rear



Radio/CD/USB



Engine Management Lights



Central Air Vent

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774

DEKRA

CONDITION REPORT

Report No:
2017317189
DATE
27/10/2026



Door Panel Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHCT41DLKU480774