DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	KS32ZVGP
Model	STARIA 2.2 EXECUTIVE 11-S DSL AT [2021-2026]	Register Number	
		Date Of First Licensing	
VIN	KMHYC811MNU054664	Last COR	
Engine Number		License Expiry Date	31/08/2026
Doors	5	Power / Displacement	
Color	WHITE	Paint Finish	TWO COAT UNI
Year Model	2022	Fuel	DIESEL
Km Reading	158,300 KM	Transmission	AUTOMATIC
Cab / Body Type	STATION WAGON		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026





Damage	Repair Way
Engine Oil Sweat	Repair
Engine Wiring Defective	Repair
Hoses Oil Leak	Replace
Windscreen Wiper Missing	Replace
Indicator Light Front Left Cracked	Replace
Tail Light Left Damaged	Replace
Tail Light Right Cracked	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Front Bumper Residual Traces of Repair	Repair
Rear Fender Left Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Front Fender Left / Inner Tray Welded	Repair
Rear Fender Left / Inner Tray Damaged	Repair
Door Front Left Residual Traces of Repair	Repair
Door Front Right Paintwork • Chipmarks	Repair
Door Rear Left Dented	Repair
Door Rear Right Residual Traces of Repair	Repair
Windscreen Chipped	Repair
Back Window Scratched	Repair
Shock Absorber Rear Left Damaged	Replace
Control Arm Bush(es) Front Axle Right Cracked	Replace
Tyre Front Left Worn	Replace
Tyre Rear Left Damaged	Replace
Spare Tyre Worn	Replace
Rim Front Right Scratched	Repair
Rim Rear Right Scratched	Repair
Sub Frame Damaged	Repair
Belly plates Damaged	Replace
Fuel Tank Damaged	Repair
Rear right shock absorber weak	Replace
Fuel tank strap damaged	Repair
Warning light illuminated on dashboard	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	4.93	5.12	-	
Rear	3.38	3.89	-	
Emergency / Parking	2.79	3.63	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/65 R17	99H	Powertrac	City Rover	V	0126	0 mm
Front Right	215/65 R17	99H	Powertrac	City Rover	V	1525	5 mm
Rear Left	215/65 R17	99H	Powertrac	City Rover	V	1525	0 mm
Rear Right	215/65 R17	99H	Powertrac	City Rover	V	0125	3 mm
Spare	215/65 R17	99H	Powertrac	City Rover	V	1006	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	IBU-TPMS(INTEGRATED BODY CONTROL UNIT-TIRE PRESSUR	B1210:00	LEFT FRONT SENSOR FAULT	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Electrical Components and Instruments: Rear left door closed sensor faulty.
Body • Exterior: Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Signs of impact damage to front of vehicle.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT


Report No:
2017316239
DATE
23/10/2026



Brake and shock absorber repor



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Automatic Transmission



90 DEGREE FRONT



90 DEGREE LEFT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026



90 DEGREE RIGHT




LR TYRE TREAD



RR TYRE TREAD



LF TYRE TREAD



RF TYRE TREAD



Spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



Front chassis



Rear chassis



Fuel tank strap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT


Report No:
2017316239
DATE
23/10/2026



Spare wheel Accessories



Oil cap and dipstick



Seat Front Right



Seat Front Right



Rim Rear Right



Rim Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026



Tail Light Left



Door Rear Right



Rear Fender Right



Door Front Right



Door Front Right



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026



Indicator Light Front Left




Door Front Left



Door Rear Left



Rear Fender Left



Seat Front Left



Seat Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026



Tail Light Right



Back Window



Windscreen Wiper



Engine Wiring



Front Fender Left / Inner Tray



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026




Control Arm Bush(es) Front Axle Right



Front Bumper



Front Bumper



Rear Fender Left / Inner Tray



Belly plates



Hoses

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026



Sub Frame



Sub Frame



Tyre Front Left



Engine



Fuel Tank



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664

DEKRA

CONDITION REPORT

Report No:
2017316239
DATE
23/10/2026




Spare Tyre



Shock Absorber Rear Left



Belly plates



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KMHYC811MNU054664