



CONDITION REPORT



Report No:
2017304693
DATE
29/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	29/09/2026		M57 Pretoria Road - 1619
Inspection Date	29/09/2026		Kempton Park - GT

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	KIA	Registration Number	JH47BXGP
Model	PICANTO	Register Number	
VIN	KNAB2511LLT565258	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/04/2025
Color	SILVER	Power / Displacement	
Year Model	2022	Paint Finish	M - METALLIC
Km Reading	202,210 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT



Report No:

2017304693

DATE

29/09/2026

Damage

Repair Way

Engine Oil Sweat	Repair
Air cleaner Damaged	Repair
Headlight Right Damaged	Replace
Seat Front Left Torn / Cut	Repair
Seat Front Right Torn / Cut	Repair
Side Mirror Left Paintwork • Flaking	Repair
Side Mirror Right Residual Traces of Repair	Repair
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Paintwork • Scratched	Repair
A • Pillar Left Dented	Repair
A • Pillar Right Residual Traces of Repair	Repair
C • Pillar Right Residual Traces of Repair	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Dented	Repair
Door Rear Right Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Sill Panel Left Dented	Repair
Roof Dented	Repair
Windscreen Cracked	Replace
Brake Pad/Shoe 2. Axle left Defective	Replace
Shock Absorber Front Left Loose / Excessive Play	Replace
Tyre Rear Left Smooth	Replace
Tyre Rear Right Excessive Wear & Tear	Replace
Spare Tyre Smooth	Replace
Rim Front Right Deformed	Repair
Gear Selections Malfunction	Repair
Some body panels misaligned	Repair
Rear tyre size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	2.6	2.6	-	
Rear	1.2	1.3	-	
Emergency / Parking	1	1.1	-	

DEKRA Automotive (PTY) Ltd.
 97 Willem Cruywagen Ave
 Klerksoord, Pretoria, 0200
 Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT



Report No:
2017304693
DATE
29/09/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82H	Firestone	Touring	V	0323	2 mm
Front Right	175/65R14	82H	Firestone	Touring	V	0323	1 mm
Rear Left	175/65R14	82H	Firestone	Touring	V	5222	0 mm
Rear Right	175/70R13	82T	Lanvigator	Catchgre	V	1015	0 mm
Spare	175/65R14	82H	Firestone	Touring	V	0000	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AIRBAG	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS. BODY EXTERIOR - SIGNS OF SPRAY WORK DONE ON BODY PANELS / RESIDUAL TRACES OF POOR REPAIR ON BODY PANELS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT



Report No:

2017304693

DATE

29/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT



Report No:

2017304693

DATE

29/09/2026



INTERIOR (FRONT DRIVER DOOR)



Manual transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



VIN PLATE OR STICKER



LICENSE DISC

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT



Report No:

2017304693

DATE

29/09/2026



ENGINE 1



ENGINE 2




CHASSIS



REAR



Oil cap and dipstick



Coolant reservoir

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT



Report No:
2017304693
DATE
29/09/2026



LF TYRE TREAD



RF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD



Sparewheel



Shock and brake report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za


VIN: KNAB2511LLT565258




CONDITION REPORT



Report No:
2017304693
DATE
29/09/2026



Diagnostic Report page 1



Diagnostic Report page 2



ADDITIONAL 12



Front Fender Right



Door Front Right



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT



Report No:
2017304693
DATE
29/09/2026



Side Mirror Right



A • Pillar Right



A • Pillar Right



C • Pillar Right



Rear Fender Right



Door Rear Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258




CONDITION REPORT



Report No:
2017304693
DATE
29/09/2026



Roof



Seat Front Right



Spare Tyre



Door Rear Left



Door Rear Left



A • Pillar Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT



Report No:

2017304693

DATE

29/09/2026



Side Mirror Left



Seat Front Left



Windscreen



Bonnet



Air cleaner



Air cleaner

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT



Report No:
2017304693
DATE
29/09/2026



Water level



Headlight Right



Rim Front Right



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT




Report No:

2017304693

DATE

29/09/2026




Front Bumper



Front Bumper



Grill



Grill



Grill



Shock Absorber Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT



Report No:
2017304693
DATE
29/09/2026



Sill Panel Left



Sill Panel Left



Sill Panel Left



Tyre Rear Left



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258



CONDITION REPORT



Report No:

2017304693

DATE

29/09/2026



Tyre Rear Right




Engine



Tyre Rear Right



Brake Pad/Shoe 2. Axle left



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LLT565258