DEKRA

CONDITION REPORT

Report No:
2017305262
DATE
30/09/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	30/09/2026		
Inspection Date	30/09/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	KIA	Registration Number	LB23PFGP
Model	PICANTO	Register Number	
VIN	KNAB2511LPT052387	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2027
Color	SILVER	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	242,710 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387

DEKRA

CONDITION REPORT

Report No:
2017305262
DATE
30/09/2026





Damage	Repair Way
Engine Oil Leak	Repair
Windscreen Wiper Worn	Replace
Number Plate Light Right Missing	Replace
Seat Front Right Torn / Cut	Repair
Side Mirror Left Paintwork • Flaking	Repair
Side Mirror Right Paintwork • Flaking	Repair
Front Bumper Damaged	Repair
Grill Damaged	Replace
Bonnet Dented	Repair
Front Fender Left Dented	Repair
Rear Fender Right Residual Traces of Repair	Repair
Roof Dented	Repair
Windscreen Chipped	Replace
Alignment Left / Right Difference out of legal range	Repair
Tyre Front Left Excessive Wear & Tear	Replace
Tyre Front Right Smooth	Replace
Tyre Rear Left Smooth	Replace
Rim Front Left Deformed	Repair
Belly plates Damaged	Replace
CV Joint(s) Boot(s) Front Right (inner/outer) Damaged	Replace
Clutch Operation Shudder	Repair
Warning lights illuminated	Repair
Front axle tyre size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.2	2.0	-	
Rear	1.8	2.0	-	
Emergency / Parking	1.3	1.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/60R14	82H	Wanli	S100	V	3216	0 mm
Front Right	175/65R14	82H	Rapid	Plus	V	0924	0 mm
Rear Left	175/65R14	82T	Dunlop	Sport	V	1820	0 mm
Rear Right	175/65R14	82T	Falken	Sincera	V	1223	1 mm
Spare	T115/70D15	99M.	Maxxis	Temporary	V	0000	1 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387

DEKRA

CONDITION REPORT

Report No:
2017305262
DATE
30/09/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	AIRBAG	B1102:00	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Rain at time of inspection
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.BODY EXTERIOR - SIGNS OF SPRAY WORK DONE ON BODY PANELS

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387

DEKRA

CONDITION REPORT

Report No:
2017305262
DATE
30/09/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387

DEKRA

CONDITION REPORT

Report No:
2017305262
DATE
30/09/2026



INTERIOR (FRONT DRIVER DOOR)



Manual transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387

DEKRA

CONDITION REPORT

Report No:
2017305262
DATE
30/09/2026



ENGINE 1




ENGINE 2




CHASSIS



REAR



Coolant reservoir



Oil cap and dipstick


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387

DEKRA

CONDITION REPORT

Report No:
2017305262
DATE
30/09/2026



LF TYRE TREAD



RF TYRE TREAD




LR TYRE TREAD



RR TYRE TREAD



Sparewheel



Shock and brake report

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387


DEKRA

CONDITION REPORT

Report No:
2017305262
DATE
30/09/2026



Diagnostic Report page 1


Diagnostic Report page 2



Battery is loose


Side Mirror Right


Seat Front Right


Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387

DEKRA

CONDITION REPORT

Report No:
2017305262
DATE
30/09/2026



Front Fender Left




Side Mirror Left



Windscreen



Tyre Front Right



CV Joint(s) Boot(s) Front Right (inner/outer)



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387


DEKRA

CONDITION REPORT


Report No:
2017305262
DATE
30/09/2026



Front Bumper



Front Bumper



Front Bumper



Grill



Tyre Front Left



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387

DEKRA

CONDITION REPORT

Report No:
2017305262
DATE
30/09/2026



Tyre Rear Left



Number Plate Light Right



Belly plates



Rim Front Left



Engine



Bonnet

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387

DEKRA

CONDITION REPORT

Report No:
2017305262
DATE
30/09/2026



Roof



Windscreen Wiper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAB2511LPT052387