DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	KIA	Registration Number	BY92CKGP
Model	CERATO 2.0 KOUP COUPE [2009-2013]	Register Number	
VIN	KNAFW612LC5571267	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	31/08/2026
Color	SILVER	Power / Displacement	
Year Model	2012	Paint Finish	TWO COAT UNI
Km Reading	201,773 KM	Fuel	PETROL
Cab / Body Type	COUPE	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026





Damage	Repair Way
Switch Electrical Window Winder front right Damaged	Replace
Indicator Light Front Right Cracked	Replace
Fog Light Front Left Defective	Repair
Fog Light Front Right Defective	Repair
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Gear Lever Dust Boot Excessive Wear & Tear	Repair
Steering Wheel Trim Excessive Wear & Tear	Repair
Side Mirror Left Paintwork • Flaking	Repair
Side Mirror Right Paintwork • Flaking	Repair
Front Bumper Damaged	Repair
Bonnet Paintwork • Chipmarks	Repair
Front Fender Right Dented	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Chipmarks	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Right Dented	Repair
Stabilizer Mounting Front Right Damaged	Replace
Ball Joint(s) Front Axle Right Cracked	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Left Damaged	Replace
Spare Tyre Damaged	Replace
Rim Rear Left Scratched	Repair
Chassis Damaged	Repair
Sub Frame Damaged	Repair
Belly plates Damaged	Repair
Fuel Tank Damaged	Replace
Engine Noise Excessive	Repair
Clutch Operation Incorrect	Repair
Triangle Missing	Replace
Rear left and right tyre sizes different	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.64	2.91	-	
Rear	1.99	1.97	-	
Emergency / Parking	1.71	2.52	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	215/45 R17	91V	Citi	Comfort	V	3118	0 mm
Front Right	215/45 R17	91V	Citi	Comfort	V	3118	0 mm
Rear Left	225/45Z R17	94W	Nexen	Nfera	V	5223	1 mm
Rear Right	215/45 R17	87H	Kumho	Solus	V	5111	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ABS(ANTI LOCK BRAKE)	C1200	LEFT FRONT VEHICLE SPEED SENSOR(VSS) CIRCUIT OPEN	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Interior: Vehicle interior dirty and panels scratched.
Body • Exterior: Dents and scratches on body panels
Tyres and Rims: Spare wheel details not visible.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual Transmission



FRONT RIGHT CORNER



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026



90 DEGREE RIGHT



REAR LEFT CORNER



90 DEGREE REAR



90 DEGREE LEFT



Front chassis



Rear chassis

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT


Report No:
2017315661
DATE
22/10/2026



Oil cap and dipstick



ENGINE 1



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2



Spare wheel and Accessories

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026



LF TYRE TREAD



LR TYRE TREAD




RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026



Gear Lever Dust Boot



Steering Wheel Trim



Seat Front Right



Door Front Right



Indicator Light Front Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026



Side Mirror Right



Bonnet



Bonnet



Side Mirror Left



Door Front Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026



Rear Fender Left



Rear bumper



Rear bumper



Rear bumper



Boot Lid / Hatch door



Boot Lid / Hatch door


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026



Rear Fender Right



Rear Fender Right



Seat Front Left



Seat Front Left



Spare Tyre



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026



Headlight Left



Fog Light Front Left



Fog Light Front Right



Sill Panel Right



Rim Rear Left



Tyre Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026



Front Bumper


Front Bumper


Front Bumper


Sub Frame


Sub Frame


Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026



Tyre Front Left



Stabilizer Mounting Front Right



Ball Joint(s) Front Axle Right



Fuel Tank



Mounting Rubber(s) Rear Axle Right



Mounting Rubber(s) Rear Axle Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026


Chassis


Tyre Rear Left


Belly plates


Water level


Water level


Switch Electrical Window Winder front right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267

DEKRA

CONDITION REPORT

Report No:
2017315661
DATE
22/10/2026



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: KNAFW612LC5571267