DEKRA

CONDITION REPORT

Report No:
2017307849
DATE
06/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	06/10/2026		
Inspection Date	06/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HAVAL	Registration Number	LD78CKGP
Model	H2 1.5 CITY [2020-2022]	Register Number	
VIN	LGWEE4A45MH907261	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/07/2026
Color	WHITE	Power / Displacement	
Year Model	2020	Paint Finish	TWO COAT UNI
Km Reading	109,274 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	MANUAL

Vehicle Options & Accessories

Items


VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No:
2017307849
DATE
06/10/2026



Damage	Repair Way
Hazard Lights Malfunction	Repair
Seat Front Right Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Damaged	Repair
B • Pillar Left Paintwork • Scratched	Repair
Front Fender Left Damaged	Repair
Front Fender Right Damaged	Repair
Door Front Right Dented	Repair
Door Rear Left Residual Traces of Repair	Repair
Door Rear Right Residual Traces of Repair	Repair
Rear bumper Damaged	Repair
Roof Damaged	Repair
Windscreen Cracked	Replace
Shock Absorber Rear Left Sweat	Replace
Shock Absorber Rear Right Sweat	Replace
Tyre Front Left Torn / Cut	Replace
Engine Noise Excessive	Repair
Deceleration parking brake defective	Repair
Warning light illuminated on dashboard	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.6	3.09	-	
Rear	2.82	3.78	-	
Emergency / Parking	1.32	1.61	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	235/55 R18	104V	Rapid	Ecosaver	V	1121	1 mm
Front Right	235/55 R18	100H	Kumho	Solus	V	4819	1 mm
Rear Left	235/55 R18	100H	Kumho	Solue	V	4720	2 mm
Rear Right	235/55 R18	100H	Kumho	Solus	V	4720	4 mm
Spare	T155/85 R18	115M	Chaoyang	Temporary	V	3720	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A45MH907261

DEKRA

CONDITION REPORT

Report No:
2017307849
DATE
06/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ECM(ENGINE CONTROL MODULE)	P147900	PLEASE REFER TO VEHICLE SERVICE MANUAL	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.RESIDUAL TRACES OF REPAIR ON BODY PANELS / STONE CHIPS AND SPRAY WORK ON BODY PANELS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A45MH907261

DEKRA

CONDITION REPORT

Report No:
2017307849
DATE
06/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A45MH907261

DEKRA

CONDITION REPORT

Report No:
2017307849
DATE
06/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A45MH907261

DEKRA

CONDITION REPORT

Report No:
2017307849
DATE
06/10/2026



ENGINE 1




Front chassis




Rear chassis



Oil cap and dipstick



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A45MH907261


DEKRA

CONDITION REPORT

Report No:
2017307849
DATE
06/10/2026




LR TYRE TREAD




RR TYRE TREAD



Spare wheel and Accessories



Brake and shock absorber repor



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A45MH907261

DEKRA

CONDITION REPORT

Report No:
2017307849
DATE
06/10/2026



DIAGNOSTIC REPORT PAGE 3



Seat Front Right



Door Rear Right



Door Front Right



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A45MH907261

DEKRA

CONDITION REPORT

Report No:
2017307849
DATE
06/10/2026



Door Rear Left



B • Pillar Left



Front Fender Left



Bonnet



Windscreen



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A45MH907261

DEKRA

CONDITION REPORT

Report No:
2017307849
DATE
06/10/2026



Front Fender Right




Water level




Front Bumper



Front Bumper



Front Bumper



Shock Absorber Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A45MH907261

DEKRA

CONDITION REPORT

Report No:
2017307849
DATE
06/10/2026



Tyre Front Left



Shock Absorber Rear Right



Water level



Hazard Lights

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A45MH907261