DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	
Requested Date	22/10/2026		-
Inspection Date	22/10/2026		-

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HAVAL	Registration Number	HT40VVGP
Model	H2	Register Number	
VIN	LGWEE4A46KH901241	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2026
Color	BROWN	Power / Displacement	
Year Model		Paint Finish	TWO COAT METALLIC
Km Reading	135,508 KM	Fuel	PETROL
Cab / Body Type	STATION WAGON	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Indicator Light Front Right Damaged	Replace
Seat Front Left Damaged	Repair
Seat Front Right Damaged	Repair
Hood Lining Defective	Repair
Door Panel Rear Right Torn / Cut	Repair
Door Sealing Rubber Front Left Damaged	Replace
Door Sealing Rubber Front Right Damaged	Replace
Door Sealing Rubber Rear Left Damaged	Replace
Door Sealing Rubber Rear Right Damaged	Replace
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Dented	Repair
Bonnet slam plate (Shock tower/ Inner tray) Defective	Repair
C • Pillar Right Dented	Repair
Front Fender Left Dented	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Residual Traces of Repair	Repair
Door Front Left Damaged	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Damaged	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Dented	Repair
Boot Lid / Hatch Door Rubbers Defective	Repair
Rear bumper Damaged	Repair
Roof Dented	Repair
Windscreen Chipped	Repair
Steering Rack Boot Right Damaged	Replace
Control Arm(s) Front Rear Left Damaged	Replace
Chassis Damaged	Repair
CV Joint(s) Boot(s) Front Right (inner/outer) Defective	Replace
Radiator Cradle Dented	Repair
Engine Noise Excessive	Repair
Jack Missing	Replace
Triangle Missing	Replace
Warning lights illuminated on dashboard	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	3.8	3.56	-	
Rear	3.12	3.28	-	
Emergency / Parking	1.58	1.87	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	235/55 R18	104W	Autogrip	Grip4000	V	0625	2 mm
Front Right	235/55 R18	104V	Nexen	Nfera	V	4723	4 mm
Rear Left	235/55 R18	104V	Nexen	Nfera	V	3622	4 mm
Rear Right	235/55 R18	100V	Atlas	Batman	V	1122	2 mm
Spare	T155/85 R18	115M	Choayang	Temporary	V	3418	4 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ESP(ELECTRONIC STABILITY PROGRAM)	C190104	PROCESSOR VOLTAGE TOO LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.POOR RESIDUAL TRACES OF REPAIR ON BODY PANELS / BODY PANELS MISALIGNED / BONNET SLAM PLATE PLASTIC COVER LOOSE.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026



INTERIOR (FRONT DRIVER DOOR)



Automatic Transmission



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241


DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026



ENGINE 1



Front chassis




Rear chassis



Oil cap and dipstick



LF TYRE TREAD



RF TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026




LR TYRE TREAD




RR TYRE TREAD



Spare wheel and Accessories



Brake and shock absorber repor



Diagnostic report page 1



Diagnostic report page 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026



Diagnostic report page 3



Seat Front Right




Door Sealing Rubber Front Right



Door Sealing Rubber Rear Right



Door Panel Rear Right



C • Pillar Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026



Rear Fender Right



Door Rear Right



Door Front Right



Door Front Right



Side Mirror Right



Indicator Light Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT


Report No:
2017315737
DATE
22/10/2026



Front Fender Right



Rear bumper



Rear bumper



Boot Lid / Hatch door



Boot Lid / Hatch Door Rubbers



Rear Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026



Door Rear Left



Door Front Left



Door Sealing Rubber Front Left



Seat Front Left



Door Sealing Rubber Rear Left



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026



Bonnet



Front Bumper



Front Bumper



Front Bumper



Windscreen



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026



Engine




Steering Rack Boot Right



CV Joint(s) Boot(s) Front Right (inner/outer)



Chassis



Control Arm(s) Front Rear Left



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241

DEKRA

CONDITION REPORT

Report No:
2017315737
DATE
22/10/2026



Water level



Bonnet slam plate (Shock tower/ Inner tray)



Hood Lining



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: LGWEE4A46KH901241