DEKRA

CONDITION REPORT

Report No:
2017316616
DATE
26/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	26/10/2026		
Inspection Date	26/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	SUZUKI	Registration Number	KSZ372MP
Model	S-PRESSO 1.0 GL+ MT [2022-ON]	Register Number	
VIN	MA3RFL61S00412813	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	GREY	Power / Displacement	
Year Model	2023	Paint Finish	M - METALLIC
Km Reading	64,154 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3RFL61S00412813

DEKRA

CONDITION REPORT

Report No:
2017316616
DATE
26/10/2026



Damage	Repair Way
Engine Oil Sweat	Repair
Boot Carpet Missing	Replace
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Scratched	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Cracked	Replace
Window Front Door Left Damaged	Replace
Back Window Damaged	Replace
Service Brake Performance Rear Axle Left / Right Difference out of legal range	Repair
Tyre Front Right Damaged	Replace
Gearbox Oil Leak	Repair
No license disc	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.0	2.1	-	
Rear	1.3	0.7	-	
Emergency / Parking	1.2	1.2	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/70R14	81S	MRF	Zvtv	V	3622	2 mm
Front Right	165/70R14	81S	MRF	Zvtv	V	3622	0 mm
Rear Left	165/70R14	81S	MRF	Zvtv	V	3622	3 mm
Rear Right	165/70R14	81S	MRF	Zvtv	V	3622	2 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3RFL61S00412813

DEKRA

CONDITION REPORT

Report No:
2017316616
DATE
26/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	C1157-1C	POWER SUPPLY VOLTAGE ABNORMAL	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3RFL61S00412813


DEKRA

CONDITION REPORT

Report No:
2017316616
DATE
26/10/2026



Shock and brake report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3RFL61S00412813

DEKRA

CONDITION REPORT

Report No:
2017316616
DATE
26/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



Manual



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3RFL61S00412813

DEKRA

CONDITION REPORT


Report No:
2017316616
DATE
26/10/2026



90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



No spare wheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3RFL61S00412813

DEKRA

CONDITION REPORT

Report No:
2017316616
DATE
26/10/2026



No license disc



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3RFL61S00412813

DEKRA

CONDITION REPORT

Report No:
2017316616
DATE
26/10/2026



Coolant bottle



Water level



Window Front Door Left



Windscreen



Back Window



Boot Carpet


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3RFL61S00412813

DEKRA

CONDITION REPORT

Report No:
2017316616
DATE
26/10/2026


side-slip test

Front axle -5 m/km Rear axle -12 m/km

Shock absorber test (MSD3000)


	left	right	Difference	Weight
Front axle	> 0,30	> 0,30	0 %	520 kg
Rear axle	0,23	> 0,30	23 %	317 kg
Total weight				837 kg

Brake test

Brake force

	left	right	Difference
Front axle	2,06 kN	2,12 kN	3 %
Parking brake	1,21 kN	1,27 kN	5 %
Rear axle	1,33 kN	0,74 kN	45 %
Final evaluation static			
Deceleration service brake		76 %	
Deceleration parking brake		30 %	Total weight 837


Service Brake Performance Rear Axle


Bonnet


Front Bumper


Front Bumper


Front Fender Left


Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3RFL61S00412813


DEKRA

CONDITION REPORT

Report No:
2017316616
DATE
26/10/2026



Door Rear Left



Rear Fender Left




Boot Lid / Hatch door



Rear bumper



Rear bumper



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3RFL61S00412813

DEKRA

CONDITION REPORT

Report No:
2017316616
DATE
26/10/2026



Door Rear Right



Door Front Right




Front Fender Right



Engine



Gearbox



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MA3RFL61S00412813