CONDITION REPORT

Report No:
2017309138
DATE
08/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park -
Requested Date	08/10/2026		
Inspection Date	08/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	FORD	Registration Number	KPY852MP
Model	ECOSPORT 1.5 TITANIUM POWERSHIFT [2014-2016]	Register Number	
		Date Of First Licensing	
VIN	MAJAXXMRKAEA53612	Last COR	
Engine Number		License Expiry Date	
Doors	5	Power / Displacement	
Color	ORANGE	Paint Finish	M - METALLIC
Year Model	2014	Fuel	PETROL
Km Reading	110,736 KM	Transmission	AUTOMATIC
Cab / Body Type	HATCHBACK		

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No:
2017309138
DATE
08/10/2026





Damage	Repair Way
Under bonnet insulation cover Damaged	Repair
Windscreen Wiper Missing	Replace
Dim and Bright Indicator Light Malfunction	Repair
Fog Light Front Left Malfunction	Repair
Fog Light Front Right Malfunction	Repair
Side Mirror Left Damaged	Repair
Front Bumper Paintwork • Scratched	Repair
Bonnet Paintwork • Discoloured	Repair
Front Fender Left Paintwork • Scratched	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Paintwork • Scratched	Repair
Windscreen Chipped	Repair
Spare Tyre Damaged	Replace
Body exterior	Vehicle got minor scratches, stone chips and dents
Body exterior	Discoloring on some body panels
Foreign substance on expansion bottle cap	Repair
Boot not opening	Repair
Engine light on	Repair
Front and rear tires deferred name brand	Repair
Antenna missing	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.8	2.7	-	
Rear	2.0	1.8	-	
Emergency / Parking	1.6	1.4	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	205/60R16	92V	Double king	Dk558	V	2921	3 mm
Front Right	205/60R16	92V	Kumho	Solus	V	2917	2 mm
Rear Left	205/60R16	92V	Toledo	Tl1000	V	1619	3 mm
Rear Right	205/60R16	92V	Toledo	Tl1000	V	3818	2 mm
Spare	205/60R16	92V	Double king	Dk558	V	2921	0 mm

* Tyre Legend: V=Virgin, R=Recap

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAEA53612

DEKRA

CONDITION REPORT

Report No:
2017309138
DATE
08/10/2026

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	CMDTCS	P0340:95-AF	CAMSHAFT POSITION SENSOR A CIRCUIT BANK 1 OR SINGL	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE: NORMAL WEAR AND TEAR MARKS ON THE BODY, INTERIOR, AND MECHANICAL.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAEA53612

DEKRA

CONDITION REPORT


Report No:
2017309138
DATE
08/10/2026



Shock and brake report



Diagnostic report



Diagnostic report



Spare wheel



Expention bottle



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAEA53612

DEKRA

CONDITION REPORT

Report No:
2017309138
DATE
08/10/2026



Automatic



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAEA53612

DEKRA

CONDITION REPORT

Report No:
2017309138
DATE
08/10/2026



90 DEGREE FRONT



90 DEGREE RIGHT




90 DEGREE REAR



90 DEGREE LEFT



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAEA53612


DEKRA

CONDITION REPORT

Report No:
2017309138
DATE
08/10/2026



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAEA53612

DEKRA

CONDITION REPORT


Report No:
2017309138
DATE
08/10/2026



CHASSIS



Water level



Under bonnet insulation cover



Bonnet



Spare Tyre



Windscreen Wiper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAEA53612

DEKRA

CONDITION REPORT

Report No:
2017309138
DATE
08/10/2026



Dim and Bright Indicator Light



Fog Light Front Left


Fog Light Front Right


Rear Fender Right


Door Rear Right


Door Front Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAEA53612

DEKRA

CONDITION REPORT

Report No:
2017309138
DATE
08/10/2026



Front Fender Right



Side Mirror Left



Front Bumper



Front Bumper



Front Fender Left



Door Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAEA53612

DEKRA

CONDITION REPORT

Report No:
2017309138
DATE
08/10/2026




Door Rear Left



Rear Fender Left



Rear bumper



Rear bumper



Boot Lid / Hatch door



Windscreen

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAJAXXMRKAEA53612