DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	14/10/2026		
Inspection Date	14/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HONDA	Registration Number	KG67DWGP
Model	AMAZE 1.2 COMFORT [2018-2021]	Register Number	
VIN	MAKDF5510J4000073	Date Of First Licensing	
Engine Number		Last COR	
Doors	4	License Expiry Date	31/12/2026
Color	SILVER	Power / Displacement	
Year Model	2019	Paint Finish	M - METALLIC
Km Reading	190,098 KM	Fuel	PETROL
Cab / Body Type	SEDAN	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026





Damage	Repair Way
Tail Light Left Damaged	Replace
Tail Light Right Defective	Repair
Headlight Left Defective	Repair
Headlight Right Damaged	Replace
Seat Front Left Dirty	Repair
Seat Front Right Torn / Cut	Repair
Seat Rear Dirty	Repair
Door Handle Rear Left Damaged	Replace
Side Mirror Right Damaged	Replace
Rear Lower Valance Damaged	Repair
Front Bumper Damaged	Repair
Grill Damaged	Repair
Bonnet Residual Traces of Repair	Repair
Front Fender Left Dented	Repair
Front Fender Right Residual Traces of Repair	Repair
Rear Fender Left Paintwork • Scratched	Repair
Rear Fender Right Dented	Repair
Rear Fender Left / Inner Tray Damaged	Repair
Door Front Left Paintwork • Scratched	Repair
Door Front Right Dented	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Damaged	Repair
Roof Dented	Repair
Parking Brake Performance Left / Right Difference out of legal range	Repair
Shock Absorber Front Left Leak	Replace
Stabilizer Mounting Front Left Damaged	Replace
Wheel bearing Front Left Loose / Excessive Play	Repair
Ball Joint(s) Front Axle Right Damaged	Replace
Tyre Front Left Smooth	Replace
Tyre Rear Right Smooth	Replace
Radiator Cross Member Deformed	Repair
Warning lights illuminated	Repair
Some body panels misaligned	Repair
Bootlid does not open	Repair
Rear tyre size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.8	2.9	-	
Rear	1.4	1.4	-	
Emergency / Parking	0.8	0.5	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	185/65R15	88H	Timax	Eco comfort	V	3522	0 mm
Front Right	185/65R15	88T	Nexen	Winguard	V	4323	1 mm
Rear Left	175/70R14	84T	MRF	ZVTV	V	3418	5 mm
Rear Right	185/65R15	88H	Pirelli	All season	V	2521	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	EPS	U3003-17	BATTERY VOLTAGE HIGH	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Residual traces of poor repair on body panels. Signs of spray work done on body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026



Shock and brake report




Diagnostics report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026



ODOMETER


Manual transmission



90 DEGREE FRONT


90 DEGREE RIGHT



90 DEGREE REAR


90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073


DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



LICENSE DISC



VIN PLATE OR STICKER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026



ENGINE 1



ENGINE 2



CHASSIS



REAR



Oil cap and dipstick



Coolant reservoir

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT


Report No:
2017312029
DATE
14/10/2026



Dent sparewheel well



Warning lights illuminated




Shock absorber test (MSD3000)

	left	right	Difference	Weight
Front axle	0,15	0,13	13 %	576 kg
Rear axle	0,28	0,22	21 %	357 kg
Total weight				933 kg

Brake test

	Brake force left	Brake force right	Difference
Front axle	2,89 kN	2,94 kN	2 %
Parking brake	0,83 kN	0,54 kN	35 %
Rear axle	1,46 kN	1,45 kN	1 %
Final evaluation static			
Deceleration service brake		96 %	
Deceleration parking brake		15 %	Total weight

Parking Brake Performance



Headlight Left



Seat Rear



Door Handle Rear Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026




Seat Front Left



Seat Front Right



Side Mirror Right



Front Fender Right



Door Front Right



Door Rear Right


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026



Rear Fender Right




Tail Light Right



Tail Light Right



Tail Light Left



Tail Light Left



Boot Lid / Hatch door

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026



Rear Fender Left




Door Rear Left



Roof



Door Front Left



Front Fender Left



Roof

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073


DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026



Bonnet



Bonnet



Bonnet



Headlight Right



Ball Joint(s) Front Axle Right



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026



Front Bumper



Front Bumper



Front Bumper



Front Bumper



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026



Front Bumper



Grill




Tyre Front Left



Shock Absorber Front Left



Shock Absorber Front Left



Stabilizer Mounting Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT


Report No:
2017312029
DATE
14/10/2026



Stabilizer Mounting Front Left



Rear bumper



Rear bumper



Rear bumper



Rear bumper



Radiator Cross Member


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026



Radiator Cross Member



Radiator Cross Member



Tyre Rear Right



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073

DEKRA

CONDITION REPORT

Report No:
2017312029
DATE
14/10/2026



Rear Lower Valance



Rear Lower Valance



Rear Fender Left / Inner Tray



Rear Fender Left / Inner Tray



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MAKDF5510J4000073