DEKRA

CONDITION REPORT

Report No:
2017316027
DATE
27/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	27/10/2026		
Inspection Date	27/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC
Manufacturer	HYUNDAI	Registration Number	JD27TZGP
Model	GRAND I10	Register Number	
VIN	MALA851ALKM030750	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	WHITE	Power / Displacement	
Year Model	2026	Paint Finish	C - COMMON
Km Reading	147,198 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

DEKRA

CONDITION REPORT

Report No:
2017316027
DATE
27/10/2026





Damage	Repair Way
Windscreen Wiper Damaged	Replace
Hazard Lights Malfunction	Repair
Headlight Left Damaged	Replace
Parcel Tray Missing	Repair
Side Mirror Left Damaged	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Repair
Bonnet Dented	Repair
Front Fender Left Damaged	Repair
Front Fender Right Dented	Repair
Rear Fender Left Dented	Repair
Rear Fender Right Paintwork • Scratched	Repair
Door Front Left Dented	Repair
Door Front Right Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Dented	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Paintwork • Scratched	Repair
Sill Panel Left Dented	Repair
Sill Panel Right Dented	Repair
Alignment Poor Alignment	Repair
Tyre Front Left Smooth	Repair
Tyre Rear Left Smooth	Replace
Engine to silencer pipe Defective	Repair
Gearbox Oil Leak	Repair
Radiator Cradle Dented	Repair
No license disc	Replace
Boot not opening can not see spare wheel	Repair
ABS light and Boot light on	Repair
All four hup caps missing	Replace
Antenna missing	Replace
Both front fender liner damage	Replace
Boot panels missing	Replace
Rear and Front tyres size differs	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	**Braking Force [KN]**	**Axle Weight [KG]**	**Deceleration [m/s²]**
Front	2.1	1.7	-	
Rear	1.7	1.9	-	
Emergency / Parking	0.8	0.9	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851ALKM030750

DEKRA

CONDITION REPORT

Report No:
2017316027
DATE
27/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	175/65R14	82H	Sailun	Antares 86	V	3020	0 mm
Front Right	185/65R15	92T	Barum	Brilliants	V	3020	4 mm
Rear Left	175/65R14	82T	Hankook	Ventus	V	4017	0 mm
Rear Right	175/70R13	82T	Matador	Stella	V	4511	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	HISTORY	C1102	BATTERY VOLTAGE LOW	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Body • Exterior: Signs of spray work done on some body panels.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851ALKM030750


DEKRA

CONDITION REPORT


Report No:
2017316027
DATE
27/10/2026



Shock and brake report



Diagnostic report



Diagnostic report



FRONT RIGHT CORNER



REAR LEFT CORNER



INTERIOR (FRONT DRIVER DOOR)

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851ALKM030750

DEKRA

CONDITION REPORT

Report No:
2017316027
DATE
27/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



MANUAL



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851ALKM030750


DEKRA

CONDITION REPORT

Report No:
2017316027
DATE
27/10/2026




90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



No license disc

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851ALKM030750

DEKRA

CONDITION REPORT

Report No:
2017316027
DATE
27/10/2026



VIN PLATE OR STICKER




ENGINE 1



ENGINE 2



CHASSIS



Coolant bottle



Oil cap and dipstick

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851ALKM030750

DEKRA

CONDITION REPORT

Report No:
2017316027
DATE
27/10/2026



Water level



Headlight Left



Bonnet



Windscreen Wiper



Side Mirror Right



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851ALKM030750

DEKRA

CONDITION REPORT

Report No:
2017316027
DATE
27/10/2026



Door Rear Right



Door Front Right



Front Fender Right



Front Bumper



Front Bumper



Front Fender Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851ALKM030750

DEKRA

CONDITION REPORT

Report No:
2017316027
DATE
27/10/2026



Side Mirror Left



Door Front Left



Door Rear Left



Rear Fender Left



Sill Panel Left



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851ALKM030750

DEKRA

CONDITION REPORT


Report No:
2017316027
DATE
27/10/2026



Rear bumper



Boot Lid / Hatch door



Sill Panel Right



Tyre Rear Left



Engine to silencer pipe



Tyre Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851ALKM030750

DEKRA

CONDITION REPORT

Report No:
2017316027
DATE
27/10/2026



Radiator Cradle



Gearbox



Parcel Tray



Hazard Lights

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851ALKM030750