DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	22/10/2026		
Inspection Date	22/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	HYUNDAI	Registration Number	KC87FXGP
Model	GRAND I10 1.25 FLUID 5-DR [2014-2017]	Register Number	
VIN	MALA851CLGM388516	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	
Color	SILVER	Power / Displacement	
Year Model	2016	Paint Finish	TWO COAT UNI
Km Reading	31,056 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026





Damage	Repair Way
Engine Oil Leak	Repair
Engine Wiring Defective	Repair
Hoses Defective	Replace
Battery clamps Defective	Repair
Air cleaner Defective	Repair
Central Air Vent Defective	Repair
Switch Electrical Window Winder rear right Damaged	Replace
Windscreen Wiper Missing	Replace
Air Conditioner Insufficient	Replace
Headlight Left Defective	Repair
Headlight Right Defective	Repair
Seat Front Right Torn / Cut	Repair
Seat Rear Torn / Cut	Repair
Seat Belt Rear Left Torn / Cut	Replace
Door Sealing Rubber Front Right Damaged	Replace
Door Sealing Rubber Rear Left Damaged	Replace
Parcel Tray Damaged	Repair
Side Mirror Right Paintwork • Scratched	Repair
Front Bumper Damaged	Replace
Bonnet Paintwork • Chipmarks	Repair
Firewall Damaged	Repair
A • Pillar Left Dented	Repair
C • Pillar Left Dented	Repair
Front Fender Left Residual Traces of Repair	Repair
Front Fender Right Damaged	Repair
Rear Fender Left Damaged	Repair
Rear Fender Right Damaged	Repair
Front Fender Left / Inner Tray Damaged	Replace
Front Fender Right / Inner Tray Damaged	Replace
Door Front Right Residual Traces of Repair	Repair
Door Rear Left Paintwork • Scratched	Repair
Door Rear Right Damaged	Repair
Boot Lid / Hatch door Dented	Repair
Rear bumper Damaged	Repair
Inner Boot Floor Pan and Spare Wheel Well Dented	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Roof Residual Traces of Repair	Repair
Stabilizer Mounting Front Right Damaged	Replace
Mounting Rubber(s) Rear Axle Left Cracked	Replace
Mounting Rubber(s) Rear Axle Right Cracked	Replace
Tyre Front Left Worn	Replace
Tyre Front Right Damaged	Replace
Tyre Rear Right Worn	Replace
Rim Front Left Scratched	Repair
Rim Front Right Scratched	Repair
Rim Rear Left Scratched	Repair
Rim Rear Right Scratched	Repair
Chassis Damaged	Repair
Sub Frame Damaged	Replace
Engine mountings Loose / Excessive Play	Repair
Belly plates Damaged	Replace
Gearbox Oil Leak	Repair
Fuel Tank Damaged	Replace
Radiator Cradle Damaged	Replace
Engine Noise Excessive	Repair

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026

Damage	Repair Way
Engine Smoke Excessive	Repair
ABS warning light illuminated on dashboard	Repair
Front and rear tyre sizes different	Repair

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.32	2.64	-	
Rear	1.61	1.93	-	
Emergency / Parking	0.78	0.87	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/65 R14	79T	Cachland	All season	V	4318	0 mm
Front Right	165/65 R14	79T	Nexen	Winguard	V	3315	0 mm
Rear Left	165/60 R14	75H	Tracmax	X-privilo	V	1824	4 mm
Rear Right	165/60 R14	75H	Sava	Intense	V	4716	0 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENG(ENGINE)	P0011	INTAKE CAMSHAFT POSITION(CMP) A TIMING OVER-ADVANC	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.Engine Compartment: Battery loose.Some bolts missing on bottom of engine.Traces of repair work done to engine.
Lights: Front left and right headlight lenses faded.
Body • Exterior: Boot does not open.Poor residual traces of repair on body panels.Body panels misaligned.Stone chips and spray work on body panels.Dents and scratches on body panels.Signs of impact damage to front of vehicle.
Road Test: Vehicle struggles to start.Gear selection faulty.

Concluding Remarks

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Sibusiso Mokase

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE REAR



90 DEGREE FRONT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



INTERIOR (FRONT DRIVER DOOR)



Manual Transmission



LF TYRE TREAD



LR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



RF TYRE TREAD



RR TYRE TREAD



Front chassis



Rear chassis



Oil cap and dipstick



ENGINE 1

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT


Report No:
2017316060
DATE
22/10/2026



VIN PLATE OR STICKER




LICENSE DISC



SHOCK AND BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2



Central Air Vent

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



Central Air Vent



Central Air Vent



Door Sealing Rubber Front Right



Seat Front Right



Seat Front Right



Seat Rear

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT


Report No:
2017316060
DATE
22/10/2026



Seat Rear




Switch Electrical Window Winder rear right




Rear Fender Right



Door Rear Right



Door Front Right



Front Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



Side Mirror Right



Rim Front Right



Bonnet



Bonnet



Front Fender Left



Rim Front Left

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



Rim Rear Left



Door Rear Left



Door Rear Left



Rear Fender Left



A • Pillar Left



Seat Belt Rear Left


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



Door Sealing Rubber Rear Left



C • Pillar Left



Rear bumper



Rear bumper



Rear bumper



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



Boot Lid / Hatch door



Windscreen Wiper




Rim Rear Right



Parcel Tray



Headlight Left



Headlight Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



Battery clamps



Engine mountings



Air cleaner



Engine Wiring



Engine Wiring



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



Roof



Air Conditioner



Tyre Front Right



Front Fender Right / Inner Tray



Front Bumper



Front Bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT


Report No:
2017316060
DATE
22/10/2026



Front Bumper



Hoses



Front Fender Left / Inner Tray



Sill Panel Left



Sill Panel Right



Sill Panel Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026




Radiator Cradle



Belly plates



Gearbox



Belly plates



Engine



Sub Frame

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



Sub Frame



Chassis



Chassis



Chassis



Fuel Tank



Mounting Rubber(s) Rear Axle Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516


DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



Mounting Rubber(s) Rear Axle Left



Tyre Rear Right



Inner Boot Floor Pan and Spare Wheel Well



Inner Boot Floor Pan and Spare Wheel Well



Chassis



Tyre Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516

DEKRA

CONDITION REPORT

Report No:
2017316060
DATE
22/10/2026



Tyre Front Left



Radiator Cradle



Firewall



Radiator Cradle



Stabilizer Mounting Front Right



Water level

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALA851CLGM388516