DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572







Assignment

Client	MFC Auction House	Inspection Location	MFC M57 Pretoria Road - 1619 Kempton Park - GT
Requested Date	23/10/2026		
Inspection Date	23/10/2026		

Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	
Manufacturer	HYUNDAI	Registration Number	FP02ZCGP
Model	I10 1.1 MOTION 5-DR [2011-2018]	Register Number	
VIN	MALAN51BLHM691769	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	30/06/2026
Color	WHITE	Power / Displacement	
Year Model	2016	Paint Finish	C - COMMON
Km Reading	128,857 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	MANUAL

Vehicle Options & Accessories

Items

VEHICLE INSPECTION


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026





Damage	Repair Way
Battery clamps Defective	Repair
Windscreen Wiper Worn	Replace
Fog Light Front Right Defective	Repair
Seat Front Right Torn / Cut	Repair
Side Mirror Left Paintwork • Scratched	Repair
Side Mirror Right Cracked	Repair
Front Bumper Residual Traces of Repair	Repair
Bonnet Residual Traces of Repair	Repair
A • Pillar Right Dented	Repair
Front Fender Right Paintwork • Scratched	Repair
Rear Fender Right Paintwork • Scratched	Repair
Front Fender Left / Inner Tray Damaged	Replace
Front Fender Right / Inner Tray Damaged	Repair
Door Front Right Paintwork • Chipmarks	Repair
Door Rear Right Paintwork • Scratched	Repair
Boot Lid / Hatch door Paintwork • Scratched	Repair
Rear bumper Cracked	Repair
Sill Panel Left Damaged	Repair
Sill Panel Right Damaged	Repair
Windscreen Cracked	Replace
Tie Rod End right Defective	Replace
Stabilizer Mounting Front Left Defective	Replace
Stabilizer Mounting Front Right Defective	Repair
Chassis Dented	Repair
Silencer Cracked	Replace
Belly plates Damaged	Replace
Gearbox Oil Sweat	Repair
Radiator Cradle Broken	Replace
Jack Missing	Replace
Wheel Spanner Missing	Replace
Triangle Missing	Replace
Battery loose	Repair
Rear wiper worn	Replace

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s²]
Front	2.0	2.4	-	
Rear	0.8	0.7	-	
Emergency / Parking	0.9	0.6	-	

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	165/60R14	75H	FIRESMAX	FM601	V	4625	3 mm
Front Right	165/60R14	75H	FIREMAX	FM601	V	4425	3 mm
Rear Left	165/60R14	75H	FIREMAX	FM601	V	4625	3 mm
Rear Right	165/60R14	75H	FIREMAX	FM601	V	4625	3 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic the following error messages were detected: (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

No	System	Code	Description	Status
1	ENG(ENGINE)	P0131	OXYGEN SENSOR CIRCUIT VOLTAGE LOW(BANK 1 SENSOR)	

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.SIGNS OF POSSIBLE IMPACT DAMAGE IN FRONT OF VEHICLE

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Boitumelo Kutumela

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026



FRONT RIGHT CORNER



REAR LEFT CORNER



90 DEGREE FRONT



90 DEGREE REAR



90 DEGREE RIGHT



90 DEGREE LEFT

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769


DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026



INTERIOR (FRONT DRIVER DOOR)



Manual



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



LICENSE DISC



VIN PLATE OR STICKER


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026



Brake report



Diagnostics report



ENGINE 1



ENGINE 2



Chasis



CHASSIS


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT


Report No:
2017316371
DATE
23/10/2026



Oil cap and dipstick




Battery



LF TYRE TREAD



RF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026



Sparewheel



Front Bumper



Front Bumper



Front Bumper



Boot Lid / Hatch door



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769


DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026



Rear bumper



Rear bumper



Rear bumper



Windscreen Wiper



Windscreen Wiper



Rear Fender Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026




Door Rear Right




Door Front Right




A • Pillar Right



A • Pillar Right



Side Mirror Right



Side Mirror Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026



Front Fender Right



Bonnet



Bonnet



Battery clamps



Water level



Water level


DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT


Report No:
2017316371
DATE
23/10/2026




Seat Front Right



Stabilizer Mounting Front Left



Stabilizer Mounting Front Right



Tie Rod End right



Belly plates



Belly plates

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026



Front Fender Left / Inner Tray



Front Fender Right / Inner Tray



Gearbox



Silencer



Silencer



Rear bumper

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026



Sill Panel Right



Sill Panel Left



Sill Panel Left



Sill Panel Left



Chassis



Radiator Cradle

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769

DEKRA

CONDITION REPORT

Report No:
2017316371
DATE
23/10/2026



Radiator Cradle



Windscreen



Windscreen



Side Mirror Left



Fog Light Front Right

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: MALAN51BLHM691769